



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 642R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR WINDSCREEN MOULDING	NECESSARY	115.00	115.00
1	REAR BOOT	DENTED	1,400.00	1,272.00
1	REAR BOOT LOGO	NECESSARY	45.00	45.00
1	REAR BUMPER	BROKEN	595.00	543.00
1	REAR BUMPER RETAINER LHS	BROKEN	95.00	95.00
1	REAR BUMPER RETAINER RHS	NOT NECESSARY	95.00	-
1	REAR END PANEL	NOT NECESSARY	467.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	245.00	-
1	REAR TAILLAMP LHS (ADDITIONAL)	BROKEN	318.99	318.99
	LESS 25% DISCOUNT		-844.00	-597.25
			2,531.99	1,791.74
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NO PLATE (SN)	CUT	35.00	35.00
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	35.00	35.00
			270.00	270.00
	<b><u>LABOUR</u></b>			
	REMOVE AND REINSTALL REAR WINDSCREEN.		120.00	120.00
	CHECK WIRING FUNCTION.		40.00	30.00
	REMOVE AND INSTALL CUSHIONS, SEATS BACK REST, INNER TRIM, GARNISH, ROOF LINING AND UPHOLSTERY TO FACILITATE REPAIR.		180.00	50.00
	APPLY RUST-PROOFING.		120.00	30.00
	REMOVE NECESSARY PARTS: JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR INNER PANEL, SPARE TYRE COMPARTMENT INCLUSIVE REPLACING THE ABOVE.		800.00	500.00
	PUTTY AND RESPRAY REAR INNER PANEL, REAR END PANEL, REAR BOOT, REAR BUMPER AND SPARE TYRE COMPARTMENT.		800.00	600.00
	REPAIR REAR FENDER LHS. (ADDITIONAL)		80.00	80.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND RESPRAY REAR FENDER LHS. (ADDITIONAL)		200.00	200.00
			2,340.00	1,610.00
<b>GRAND TOTAL</b>			<b>5,141.99</b>	<b>3,671.74</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,950.00</b>

Report Ref No. CS/FCI22004875/Eny3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.