



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1610A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	796.70	580.00
1	FRONT BUMPER SPONGE	CRACKED	394.20	125.00
1	FRONT BUMPER N/S RETAINER	DAMAGED	86.70	45.00
1	FRONT N/S HEAD LAMP	CUT	766.00	766.00
1	FRONT N/S FENDER	BUCKLED	1,446.30	809.00
1	FRONT N/S FENDER INNER TRIM	TORN	135.60	135.60
1	FRONT N/S FOG LAMP COVER	NOT NECESSARY	80.20	-
1	FRONT N/S FOG LAMP (ADDITIONAL)	CRACKED	280.20	280.20
1	FRONT N/S FOG LAMP GARNISH (ADDITIONAL)	DEFORMED	90.40	90.40
	LESS 25% DISCOUNT		-1,019.08	-707.80
			3,057.22	2,123.40
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
6	FRONT N/S FENDER INNER TRIM CLIPS (SN)	NECESSARY	30.00	30.00
			60.00	60.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE FRONT DAMAGE PARTS.		800.00	400.00
	TO SPRAY PAINTING.		800.00	400.00
	TO CHECK WIRING.		50.00	30.00
	TO APPLY ANTI RUST.	NOT NECESSARY	50.00	-
			1,700.00	830.00
	GRAND TOTAL		4,817.22	3,013.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS/AGI22004876/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.