



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 7044D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER (CONSISTENT)	SERVICEABLE	220.00	-
1	FRONT FENDER SITE COVER - R/H (CONSISTENT)	CUT	80.00	80.00
1	FRONT FORK ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	3,450.00	-
1	FRONT FORK UNDER BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	1,060.00	-
1	FRONT RIM (CONSISTENT)	NOT NECESSARY	1,250.00	-
1	FRONT RIM SHAFT (CONSISTENT)	CUT	165.00	165.00
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	98.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	420.00	-
1	HANDLE BAR (CONSISTENT)	BENT	260.00	250.00
1	HANDLE BAR END (1SET) (CONSISTENT)	CUT	136.00	136.00
1	HAND GRIP (1SET) (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT SIGNALS (N/S) (CONSISTENT)	CUT	260.00	90.00
1	CLUTCH LEVER (CONSISTENT)	BENT	108.00	108.00
1	FUEL TANK COVER - L/H (CONSISTENT)	CUT	320.00	320.00
1	FRONT FOOTREST - L/H (CONSISTENT)	CUT	128.00	60.00
1	FRONT FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	180.00	-
1	GEAR PEDAL (CONSISTENT)	CUT	180.00	140.00
1	SIDE STAND (CONSISTENT)	TO REPAIR SEE LABOUR	168.00	-
1	REAR FOOTREST - L/H (CONSISTENT)	CUT	98.00	60.00
1	REAR FOOTREST BRACKET (CONSISTENT)	CUT	220.00	175.00
	LESS 10% DISCOUNT		-888.10	-158.40
			7,992.90	1,425.60
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE (1SET) (SN) (CONSISTENT)	NOT NECESSARY	38.00	-
2	FORK OIL @\$21.00 (SN) (CONSISTENT)	NOT NECESSARY	42.00	-
2	FORK OIL SEAL @\$34.00 (SN) (CONSISTENT)	NOT NECESSARY	68.00	-
1	STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	120.00	-

Report Ref No. CS/ASM22004878/Utc4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	E.R.P. IU (SN) (CONSISTENT) <u>LABOUR</u> TO PROVIDE TOWING SERVICE (LOD). TO CHECK WIRING AND RESET HEADLAMP FOCUSING. TO REPAIR BODY FRAME. TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY, FRONT FORK UNDER BRACKET AND SIDE STAND.	CUT	180.00	165.00
			448.00	165.00
		NOT NECESSARY NOT NECESSARY	-	-
			80.00	-
			480.00	-
			620.00	300.00
			1,180.00	300.00
GRAND TOTAL		9,620.90	1,890.60	

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,620.90	1,890.60
---	--	--	----------	----------

Report Ref No. CS/ASM22004878/Utc4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.