

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004881/RNY3Q2**Date:** 30/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00094542100

Claimant Vehicle No : SMY483D **Insured Vehicle No :** GBG5621P

Date of Loss: 17/05/2022 Nature of Claim: TP Claim No: SNM22D203467/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY483D**

Make & Model: TOYOTA YARIS, 1.3 (A) Engine No: M15AY111090

Reg. Date: 09/02/2021 (Man. Year: 2020) Chassis No: JTDKBAB370L003122

Colour: Red Odometer: 57161 km

Engine Capacity: 1490 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,894.90	5,328.43	9,566.47	64.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,260.00	2,500.00	2,760.00	52.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,154.90	7,828.43	12,326.47	61.16
Approved Total (Overridden) (\$\$)		6,250.00		
(\$\$)	20,154.90	6,250.00	13,904.90	68.99
+ GST 7.00/7.00% (\$\$)	1,410.84	437.50	973.34	68.99
Nett Amount (\$\$)	21,565.74	6,687.50	14,878.24	68.99

INSPECTION

Date of Assignment: 24/05/2022

Date Inspected: 24/05/2022 Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2022)
Parts:	144	TOYOTA YARIS 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY483D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,879.00 FL	*1,543.90 FL
2	1		*TAILGATE INNER LOCK	Cut	354.00 FL	*354.00 FL
3	1		*TAILGATE WEATHERSTRIP	Necessary	350.00 FL	*350.00 FL
4	1		*TAILGATE OUTER GARNISH	Scratched	398.00 FL	*398.00 FL
5	1		*TAILGATE LOGO	Necessary	80.00 FL	*62.20 FL
6	1		*TAILGATE EMBLEM CROSS	Necessary	65.00 FL	*65.00 FL
7	1		*TAILGATE EMBLEM YARIS	Necessary	68.00 FL	*68.00 FL
8	1		*TAILGATE EMBLEM HYBRID	Necessary	69.00 FL	*69.00 FL
9	1		*TAILGATE WINDSCREEN MOULDING	Necessary	212.00 FL	*169.20 FL
10	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	82.00 FL	*- FL
11	1		*TAILGATE LAMP	O/S Cracked	974.00 FL	*398.40 FL
12	1		*TAILGATE INNER TRIM BOARD	Cut	551.00 FL	*378.90 FL
13	1		*REAR BUMPER	Deformed	1,125.00 FL	*503.04 FL
14	1		*REAR BUMPER LOWER	Deformed	685.00 FL	*541.10 FL
15	2		*REAR BUMPER BRACKET	Not Necessary	380.00 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER	Not Necessary	150.00 FL	*- FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	136.00 FL	*- FL
18	2		*TAILAMP LOWER BRACKET	Not Necessary	318.00 FL	*- FL
19	2		*TAILAMP	Not Necessary	1,774.00 FL	*- FL
20	1		*TAILAMP PANEL RH	Not Necessary	398.00 FL	*- FL
21	2		*REAR FENDER	Repair	798.00 FL	*- FL
22	2		*REAR FENDER INNER COWLING	Not Necessary	140.00 FL	*- FL
23	1		*REAR FENDER INNER TRIM LH (BOTTOM)	Not Necessary	871.00 FL	*- FL
24	1		*REAR FENDER ARCH GARNISH	N/S Cracked	796.00 FL	*371.00 FL
25	1		*REAR FENDER AIR VENT LH	Not Necessary	159.00 FL	*- FL
26	1		*REAR END PANEL OUTER	Bent	678.00 FL	*612.00 FL
27	1		*REAR END PANEL INNER	Not Necessary	411.00 FL	*- FL
28	1		*REAR END PANEL SIDE EXTENSION RH	Not Necessary	359.00 FL	*- FL
29	1		*REAR END PANEL TOP GARNISH	Deformed	398.00 FL	*343.90 FL
30	1		*REAR SPARE TYRE BOLT	Not Necessary	45.00 FL	*- FL
31	1		*REAR FLOOR PANEL	Repair	1,245.00 FL	*- FL
32	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	480.00 FL	*- FL
33	1		*REAR FLOOR LOWER COVER	Deformed	481.00 FL	*423.60 FL
34	2		*REAR TOOLS BOX	Not Necessary	722.20 FL	*- FL
35	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
36	1		*TAILGATE INNER TRIM CLIP (18 PCS)	Necessary	117.00 FS	*30.00 FS
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
39	1		*TAILGATE INNER TRIM CLIPS	Repeated	50.00 FS	*- FS
40	18		*REAR FENDER INNER TRIM CLIPS	Not Necessary	117.00 FS	*- FS
41	18		*REAR FENDER INNER COWLING CLIP	Not Necessary	117.00 FS	*- FS
42	1		*REAR END PANEL TOP GARNISH CLIPS (3 PCS)	Necessary	25.50 FS	*20.00 FS
43	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
44	1		*REAR FLOOR PANEL INSULATOR SEAL	Not Necessary	250.00 FS	*- FS
45	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

Report was unsubmitted during this print-out.

9/30/22, 2:31 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REVERSE SENSOR	Not Working	220.00 FS	*220.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					19,302.70	6,991.24
- List Item Discount on L Items 25.00/25.00% (\$)					4,407.80	1,662.81
Total Parts (\$)					14,894.90	5,328.43
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	2,000.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	400.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	60.00
7	TRANFER TAILGATE MECHANISM	New	80.00	60.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	30.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	80.00
Gross Labour Cost (\$\$)			5,260.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >