

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004883/BQY3Q2**Date:** 25/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00235102100
Claimant Vehicle No :	GBH4167K	Insured Vehicle No :	SMY9293B
Date of Loss:	22/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203531/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4167K	Engine No:	R06A2165066
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	DA17V821962
Reg. Date:	04/06/2018 (Man. Year: 2017)	Odometer:	0 km
Colour:	White		
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	155 R12	Rear Tyre Size:	155 R12
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,408.05	8,280.03	7,128.02	46.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,200.00	3,520.00	3,680.00	51.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,608.05	11,800.03	10,808.02	47.81
Approved Total (Overridden) (\$\$)		9,450.00		
Nett Amount (\$\$)	22,608.05	9,450.00	13,158.05	58.20

INSPECTION

Date of Assignment:	10/06/2022		
Date Inspected:	25/05/2022	Inspected At:	BLK 8 KAKI BUKIT AVENUE 4 #02-16 PREMIER @ KAKI BUKIT SINGAPORE 415875 Repairer: PROMPT MOTORS (HQ)
Estimated Period of Repair:	14.0 days		

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2023)
Parts:	144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4167K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	863.00 FL	*863.00 FL
2	1		*BONNET RH HINGE	Not Damaged	55.30 FL	*- FL
3	1		*BONNET LH HINGE	Not Damaged	55.30 FL	*- FL
4	1		*BONNET EMBLEM	Necessary	34.70 FL	*34.70 FL
5	1		*BONNET LOCK	Not Damaged	65.10 FL	*- FL
6	1		*FRONT BUMPER	Dented	638.00 FL	*638.00 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	28.70 FL	*28.70 FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	28.70 FL	*28.70 FL
10	1		*RH HEADLAMP	Broken	374.20 FL	*374.20 FL
11	1		*LH HEADLAMP	Broken	374.20 FL	*374.20 FL
12	1		*SUPPORT PANEL	Bent	550.60 FL	*550.60 FL
13	1		*AIRCON CONDENSER	Bent	623.10 FL	*623.10 FL
14	1		*RADIATOR ASSY	Bent	732.40 FL	*480.00 FL
15	1		*FRONT RH FENDER	Not Damaged	383.40 FL	*- FL
16	1		*FRONT RH FENDER SPLASH SHIELD	Broken	74.00 FL	*74.00 FL
17	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	30.00 FL	*20.00 FL
18	1		*TAILGATE	Dented	986.10 FL	*899.00 FL
19	1		*TAILGATE LOCK	Jammed	178.30 FL	*178.30 FL
20	1		*TAILGATE LOCK CATCH	Not Damaged	35.50 FL	*- FL
21	1		*TAILGATE OUTER HANDLE	Not Damaged	78.40 FL	*- FL
22	1		*TAILGATE WEATHERSTRIP	Torn	144.90 FL	*144.90 FL
23	1		*REAR BUMPER	Dented	594.30 FL	*594.30 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
25	1		*REAR BUMPER RH RETAINER	Necessary	33.40 FL	*33.40 FL
26	1		*REAR BUMPER LH RETAINER	Necessary	33.40 FL	*33.40 FL
27	1		*REAR BUMPER LH LAMP	Broken	99.40 FL	*99.40 FL
28	1		*REAR BUMPER RH LAMP	Broken	99.40 FL	*99.40 FL
29	1		*REAR BUMPER NUMBER PLATE LAMP	Not Damaged	35.80 FL	*- FL
30	1		*REAR BUMPER NUMBER PLATE LAMP BRACKET	Not Damaged	28.70 FL	*- FL
31	1		*END PANEL	Dented	654.90 FL	*543.00 FL
32	1		*END PANEL LH AIR DUCT	Not Damaged	42.10 FL	*- FL
33	1		*END PANEL RH AIR DUCT	Broken	42.10 FL	*42.10 FL
34	1		*EXHAUST SILENCER	Bent	452.90 FL	*452.90 FL
35	1		*EXHAUST SILENCER GASKET	Necessary	48.00 FL	*48.00 FL
36	1		*EXHAUST SILENCER RUBBER MOUNTING	Not Necessary	29.80 FL	*- FL
37	1		*LH REAR FENDER	Not Damaged	873.60 FL	*- FL
38	1		*LH REAR FENDER INNER TRIM	Not Damaged	101.00 FL	*- FL
39	1		*SET LH REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FL	*20.00 FL
40	1		*LH REAR FENDER SPLASH SHIELD	Distorted	67.40 FL	*67.40 FL
41	1		*SET LH REAR FENDER SPLASH SHIELD CLIPS	Necessary	30.00 FL	*20.00 FL
42	1		*RH REAR FENDER	Not Damaged	873.60 FL	*- FL
43	1		*RH REAR FENDER INNER TRIM	Not Damaged	101.00 FL	*- FL
44	1		*SET RH REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FL	*20.00 FL
45	1		*RH REAR FENDER SPLASH SHIELD	Distorted	67.40 FL	*67.40 FL
46	1		*SET RH REAR FENDER SPLASH SHIELD CLIPS	Necessary	30.00 FL	*20.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SPARE TYRE CARRIAGE	Bent	377.20 FL	*195.00 FL
48	1		*FLOOR PANEL	Bent	1,372.00 FL	*1,120.00 FL
49	1		*FLOOR PANEL RH INSULATOR	Not Damaged	143.50 FL	*- FL
50	1		*FLOOR PANEL LH INSULATOR	Not Damaged	143.50 FL	*- FL
51	1		*FRONT NUMBER PLATE	Bent	70.00 FS	*40.00 FS
52	1		*RADIATOR COOLANT	Necessary	60.00 FS	*30.00 FS
53	1		*TAILGATE WORK STICKER	Necessary	1,200.00 FS	*400.00 FS
54	1		*TAILGATE 70KM/H STICKER	Necessary	28.00 FS	*10.00 FS
55	1		*TAILGATE 5 PAX STICKER	Necessary	28.00 FS	*10.00 FS
56	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
57	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
58	1		*REAR NUMBER PLATE	Necessary	70.00 FS	*40.00 FS
59	1		*SET REAR BUMPER REVERSE SENSOR	Scratched	320.00 FS	*200.00 FS
60	1		*RH REAR FENDER ADVERTISEMENT STICKER	Not Necessary	1,200.00 FS	*- FS
61	1		*RH REAR FENDER JOINT SEALANT	Not Necessary	70.00 FS	*- FS
62	1		*LH REAR FENDER ADVERTISEMENT STICKER	Not Necessary	1,200.00 FS	*- FS
63	1		*LH REAR FENDER JOINT SEALANT	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,344.30	9,607.10
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,936.25	1,327.07
Total Parts (\$\$)	15,408.05	8,280.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANEL	New	50.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR .TO REFILL AIRCON GAS	New	250.00	120.00
6	REMOVE AND REPLACE RADIATOR ASSY ,HOSES AND FAN ASSY TO ASSIST REPAIR .TO REFILL COOLANT	New	250.00	80.00
7	REFOCUS AND ADJUST HEADLAMPS ASSY	New	50.00	0.00
8	LABOUR CHARGES TO REMOVE , CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,000.00	1,000.00
9	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	800.00
10	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	0.00
11	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	0.00
12	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
13	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW DOOR	New	180.00	80.00
14	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	100.00	60.00
15	REMOVE AND REPLACE EXHAUST SILENCER AND RUBBER MOULDING TO ASSIST REPAIR	New	180.00	60.00
16	REMOVE AND REPLACE REAR INNER TRIMS AND BOARDS TO ASSIST REPAIR	New	280.00	0.00
Gross Labour Cost (S\$)			7,200.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >