11/7/22, 3:15 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22004885/KPA3Q2

07/11/2022 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0002460

Claimant Vehicle SMT9176H Insured Vehicle No: SMJ9149P

No:

Date of Loss: 19/05/2022 Nature of Claim: TP Claim No: MPC2022D0002601

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMT9176H

Make & Model: HONDA FIT, 1.5 HYBRID (A) Engine No: LEB1444118 Reg. Date: 23/07/2020 (Man. Year: 2018) Chassis No: GP51336574 22994 km Colour: Metallic Silver Odometer:

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15 Front Left Side: Rear Left Side: Yokohama 8 mm Yokohama 8 mm Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,608.88	709.52	899.36	55.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	940.00	620.00	39.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,168.88	1,649.52	1,519.36	47.95
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	3,168.88	1,300.00	1,868.88	58.98
+ GST 7.00/7.00% (S\$)	221.82	91.00	130.82	58.98
Nett Amount (S\$)	3,390.70	1,391.00	1,999.70	58.98
+ Loss of Use (4.0 x S	50.00/day) (S\$)	200.00		
+ Doc/s	Search Fee (S\$)	7.45		
N	ett Liability (S\$)	1,598.45		

INSPECTION

24/05/2022 Date of Assignment:

Bifrost Auto Pte Ltd (HQ) 176 Sin Ming Drive, #03-09 Date Inspected: 20/06/2022 Inspected At:

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

ability but any other liability under any other circumstances is hereby expressly excluded.

11/7/22, 3:15 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jul 2022)

Parts: 144 HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMT9176H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,050.20 FL	*851.10 FL
2	1		*FRONT RH DOOR FRAME TAPE	Necessary	35.80 FL	*35.80 FL
3	1		*REAR RH DOOR	Repair	899.20 FL	*- FL
4	1		*REAR RH DOOR FRAME TAPE	Not Necessary	25.90 FL	*- FL
F=Fra	nchise	part. L=ListIten	nDisc.	_		
				Sub Total (S\$)	2,011.10	886.90
	- List Item Discount on L Items 20.00/20.00% (S\$)			402.22	177.38	
				Total Parts (S\$)	1,608.88	709.52
			Report was unsubmitte	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

11/7/22, 3:15 PM

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING CHARGE	New	800.00	550.00
3	TRANSFER DOOR FITTING	New	80.00	60.00
4	ANTI-RUST	New	80.00	30.00
		Gross Labour Cost (S\$)	1,560.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >