

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004888/UEA3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210017216-01
Claimant Vehicle No :	SLN6119L	Insured Vehicle No :	SMY2608Z
Date of Loss:	21/05/2022	Nature of Claim:	TP
		Claim No:	8850049718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN6119L	Engine No:	L15B4532259
Make & Model:	HONDA HR-V, 1.5 DX CVT (A)	Chassis No:	JHMRU1810GX202259
Reg. Date:	22/05/2017 (Man. Year: 2017)	Odometer:	82307 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,393.60	2,144.88	2,248.72	51.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,130.00	700.00	38.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,223.60	3,274.88	2,948.72	47.38
+ GST 7.00/7.00% (S\$)	435.65	229.24	206.41	47.38
Nett Amount (S\$)	6,659.25	3,504.12	3,155.13	47.38
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,934.12		

INSPECTION

Date of Assignment:	24/05/2022	
Date Inspected:	24/05/2022	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	1,253.30 F	*912.60 FL
2	1		*REAR BOOT GLASS MOULDING	Necessary	96.80 F	*96.80 FL
3	1		*REAR BOOT GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
4	1		*REAR BOOT HR-VWORDING	Necessary	42.90 F	*35.00 FL
5	1		*REAR BOOT I-VTECWORDING	Necessary	48.60 F	*30.00 FL
6	1		*REAR BOOT REFLECTOR (RIGHT)	Cracked	318.50 F	*287.80 FL
7	1		*REAR BOOT LOCK	Serviceable	236.10 F	*- FL
8	1		*REAR BUMPER SIDE GARNISH (RIGHT)	Repair	182.10 F	*- FL
9	1		*REAR BUMPER	Dented	949.00 F	*829.60 FL
10	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
11	1		*REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
12	1		*REAR BUMPER REFLECTOR (RIGHT)	Cracked	151.80 F	*151.80 FL
13	1		*WEATHERSTRIPE	Serviceable	142.80 F	*- FL
14	1		*REAR END PANEL	Repair	681.70 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,393.60	2,613.60
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	468.72
Total Parts (\$)	4,393.60	2,144.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	GLASS FIXING 70 R&R	New	120.00	120.00
2	TRANSFER BOOT MECHANISM	New	150.00	60.00
3	ANTI RUST PROOF	New	80.00	30.00
4	CHECK WIRING	New	80.00	20.00
5	PANEL BEATING	New	600.00	300.00
6	PAINT WORK	New	800.00	600.00
			Gross Labour Cost (\$)	1,830.00
				1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >