

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLN 6119C  
 at Workshop m/s Styteck  
 of \_\_\_\_\_  
 Insured: SMY/26082  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLN 6119C Yr Regn: 22/05/17  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or (CA)  
 Make: Honda HRV c.c 1496  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 82307 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JHMRU1810GX202259  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_

/	
N/S	O/S
/	

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: 865k.  
 IDAC Accident Rport: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 1.3.1 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: LIA 836212  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm Rear 6 mm  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 21/05/22 D.O.I. 24/05/22  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Rec  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 20/11/20  
 No Bi SLN 6119L 0480C  
 NO Second hand parts.  
 31/5/22 p/p 83274.88 informed winston

Date/Time, File Pass to?  : Preli. Report  : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$) \_\_\_\_\_ )  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$) ) \_\_\_\_\_ \$  
 : Interview (\$) ) \_\_\_\_\_ \$  
 : Tech. Invs (\$) ) \_\_\_\_\_ \$  
 : Weekend (\$) ) \_\_\_\_\_ \$  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 ) \_\_\_\_\_ \$ + RS. \_\_\_\_\_ \$  
 ) Photos  
 ) Others  
 ) \_\_\_\_\_ \$  
 TOTAL \_\_\_\_\_

SLN6119L

Make & Model:

HONDA HRV

Chassis No:

JHMRU1810GX202259

Not Adherent  
 here  
 24/05/22  
 PIPs 3274.88  
 4 days

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Boot		912.60	\$ 1,253.30	Body ID ✓
2	Rear Boot Glass <del>Rubber</del> moulding			\$ 96.80	Rec ✓
3	Rear Boot Glass Sealant			\$ 60.00 SN	Rec 40 S/N
4	Rear Boot "HR-V" Wording		35.00	\$ 42.90	Rec ✓
5	Rear Boot "i-VTEC" Wording		30.00	\$ 48.60	Rec ✓
6	Rear Boot Reflector (Right)		287.80	\$ 318.50	one ✓
7	Rear Boot Lock			\$ 236.10	See X
8	Rear Bumper Side Garnish (Right)			\$ 182.10	R X
9	Rear Bumper		829.60	\$ 949.00	m ✓
10	Rear Bumper Clips			\$ 30.00 SN	Rec S/N
11	Rear Bumper Reverse Sencer			\$ 200.00 SN	Should S/N
12	Rear Bumper Reflector (Right)			\$ 151.80	one ✓
13	Weather Stripe			\$ 142.80	See X
14	Rear End Panel			\$ 681.70	R X
15					(202)
Labour					
1	Glass Fixing To R & R			\$ 120.00	✓
2	Transfer Boot Mechanism			\$ 150.00	60
3	Anti Rust Proof			\$ 80.00	30
4	Check Wiring			\$ 80.00	20
5	Panel Beating			\$ 600.00	300
6	Paint Work			\$ 800.00	600

**STYTECH AUTO PTE. LTD.**  
 2 Kaki Bukit Ave 2 #01-03  
 Kaki Bukit Autohub Singapore 417921  
 Tel: 6444 8125 Fax: 6445 3310  
 GST Reg. No.: 201601539K  
 Co. Reg. No.: 201601539K

22343.60  
 202  
 1874.88  
 1130270