

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004891/BQY3Q2**Date:** 06/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00003712200		
Claimant Vehicle No :	SKZ925P	Insured Vehicle No :	SMP1101Y		
Date of Loss:	21/05/2022	Nature of Claim:	TP	Claim No:	SNM22D203566/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ925P	Engine No:	G4NAFU077963
Make & Model:	HYUNDAI TUCSON, 2.0 (A)	Chassis No:	KMHJ3813MGU072594
Reg. Date:	08/01/2016 (Man. Year: 2015)	Odometer:	123655 km
Colour:	Grey		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,439.98	9,831.12	5,608.86	36.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,920.00	2,210.00	53.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,569.98	11,751.12	7,818.86	39.95
Approved Total (Overridden) (S\$)		9,400.00		
(S\$)	19,569.98	9,400.00	10,169.98	51.97
+ GST 8.00/8.00% (S\$)	1,565.60	752.00	813.60	51.97
Nett Amount (S\$)	21,135.58	10,152.00	10,983.58	51.97

INSPECTION

Date of Assignment:	30/06/2022	
Date Inspected:	25/05/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2023)
Parts:	M1-SUV	HYUNDAI TUCSON 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ925P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,758.90 FL	*1,758.90 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	143.60 FL	*143.60 FL
3	1		*TAILGATE CENTRE EMBLEM	Necessary	33.20 FL	*33.20 FL
4	1		*TAILGATE RH LAMP	Broken	932.70 FL	*932.70 FL
5	1		*TAILGATE LH LAMP	Broken	932.70 FL	*932.70 FL
6	1		*TAILGATE OUTER GARNISH	Broken	221.00 FL	*221.00 FL
7	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
8	1		*TAILGATE TUCSON EMBLEM	Necessary	29.10 FL	*29.10 FL
9	1		*TAILGATE LOCK	Jammed	677.00 FL	*192.00 FL
10	1		*TAILGATE LOCK CATCH	Not Damaged	53.00 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Not Damaged	129.50 FL	*- FL
12	1		*TAILGATE RH ELECTRONIC DAMPER	Not Damaged	1,009.59 FL	*- FL
13	1		*TAILGATE LH ELECTRONIC DAMPER	Not Damaged	1,009.59 FL	*- FL
14	1		*TAILGATE INNER TRIM BOARD	Broken	289.50 FL	*289.50 FL
15	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
16	1		*TAILGATE RH NUMBER PLATE LAMP	Not Damaged	88.40 FL	*- FL
17	1		*TAILGATE LH NUMBER PLATE LAMP	Not Damaged	88.40 FL	*- FL
18	1		*REAR BUMPER (UPPER)	Broken	447.80 FL	*447.80 FL
19	1		*SET REAR BUMPER CLIPS (UPPER)	Necessary	60.00 FL	*30.00 FL
20	1		*REAR BUMPER (LOWER)	Broken	354.60 FL	*354.60 FL
21	1		*SET REAR BUMPER CLIPS(LOWER)	Necessary	60.00 FL	*30.00 FL
22	1		*REAR BUMPER RH REFLECTOR	Broken	104.90 FL	*104.90 FL
23	1		*REAR BUMPER LH REFLECTOR	Broken	104.90 FL	*104.90 FL
24	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Damaged	140.50 FL	*- FL
25	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Scratched	140.50 FL	*140.50 FL
26	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Scratched	140.50 FL	*140.50 FL
27	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Scratched	140.50 FL	*140.50 FL
28	4		*REAR BUMPER REVERSE SENSOR HOLDERS	Not Necessary	92.00 FL	*- FL
29	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Damaged	368.70 FL	*- FL
30	1		*REAR BUMPER RH BLIND SPOT SENSOR	Not Damaged	1,397.40 FL	*- FL
31	1		*REAR BUMPER LH BLIND SPOT SENSOR	Broken	1,397.40 FL	*1,397.40 FL
32	1		*REAR BUMPER RH SIDE GARNISH	Not Damaged	22.10 FL	*- FL
33	1		*REAR BUMPER LH SIDE GARNISH	Not Damaged	22.10 FL	*- FL
34	1		*REAR BUMPER REINFORCEMENT	Broken	280.60 FL	*280.60 FL
35	1		*REAR BUMPER RH SIDE RETAINER	Necessary	26.60 FL	*26.60 FL
36	1		*REAR BUMPER LH SIDE RETAINER	Necessary	26.60 FL	*26.60 FL
37	1		*RH TAILLAMP ASSY	Broken	903.10 FL	*903.10 FL
38	1		*RH TAILLAMP SIDE GARNISH	Not Necessary	149.70 FL	*- FL
39	1		*LH TAILLAMP ASSY	Broken	903.10 FL	*903.10 FL
40	1		*LH TAILLAMP SIDE GARNISH	Not Necessary	149.70 FL	*- FL
41	1		*END PANEL	Dented	739.40 FL	*739.40 FL
42	1		*END PANEL INNER GARNISH	Broken	78.30 FL	*78.30 FL
43	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	50.00 FL	*30.00 FL
44	1		*REAR RH FENDER SPLASH SHIELD	Not Damaged	78.80 FL	*- FL
45	1		*SET REAR RH FENDER SPLASH SHIELD CLIPS	Not Damaged	20.00 FL	*- FL
46	1		*REAR RH FENDER INNER TRIM BOARD	Broken	355.40 FL	*355.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Necessary	40.00 FL	*20.00 FL
48	1		*REAR RH FENDER ARCH GARNISH	Not Damaged	67.80 FL	*- FL
49	1		*SET REAR RH FENDER ARCH GARNISH CLIPS	Not Damaged	28.00 FL	*- FL
50	1		*REAR LH FENDER SPLASH SHIELD	Not Damaged	78.80 FL	*- FL
51	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Not Damaged	20.00 FL	*- FL
52	1		*REAR LH FENDER INNER TRIM BOARD	Broken	355.40 FL	*355.40 FL
53	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	40.00 FL	*20.00 FL
54	1		*REAR LH FENDER ARCH GARNISH	Not Damaged	67.80 FL	*- FL
55	1		*SET REAR LH FENDER ARCH GARNISH CLIPS	Not Damaged	28.00 FL	*- FL
56	1		*EXHAUST SILENCER	Dented	852.80 FL	*852.80 FL
57	1		*EXHAUST SILENCER GASKET	Necessary	56.30 FL	*56.30 FL
58	1		*EXHAUST SILENCER HEAT SHIELD	No such part	131.20 FL	*- FL
59	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
60	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
61	1		*TAILGATE REVERSE CAMERA	Not Damaged	750.00 FS	*- FS
62	1		*REAR NUMBER PLATE	Dented	70.00 FS	*50.00 FS
63	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,047.48	12,251.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,607.50	2,420.28
Total Parts (\$\$)	15,439.98	9,831.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,300.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	0.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	120.00	0.00
7	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO ASSIST REPAIR	New	180.00	80.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	150.00	60.00
9	REMOVE AND REPLACE REAR INNER TRIMS GARNISH AND BOARDS TO ASSIST REPAIR	New	280.00	0.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	180.00	60.00
Gross Labour Cost (S\$)			4,130.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >