

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004896/VNY3M4**Date:** 22/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00002702200
Claimant Vehicle No :	SND7862X	Insured Vehicle No :	SLP5730S
Date of Loss:	16/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203459/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND7862X	Engine No:	L13B1606607
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GR11105065
Reg. Date:	25/01/2022 (Man. Year: 2021)	Odometer:	7563 km
Colour:	Silver		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	790.00	600.00	190.00	24.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	800.00	520.00	39.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,110.00	1,400.00	710.00	33.65
+ GST 7.00/7.00% (S\$)	147.70	98.00	49.70	33.65
Nett Amount (S\$)	2,257.70	1,498.00	759.70	33.65

INSPECTION

Date of Assignment:	24/05/2022	
Date Inspected:	30/05/2022	Inspected At: BW Workshop Services Pte Ltd (HQ) 291 Kaki Bukit Avenue 1, Shun Li Industrial Park Singapore 416080
Estimated Period of Repair:	4.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2022)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND7862X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (RH)	Dented	580.00 FL	*580.00 FL
2	1		*FRONT FENDER INNER SHIELD (RH)	Buckled	170.00 FL	*170.00 FL
3	1		*FRONT DOOR (RH) (NPA)	Repair	0.00 FL	*- FL
4	1		*FRONT RIMS (RH)	Repair	190.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					940.00	750.00
- List Item Discount on L Items 20.00/20.00% (S\$)					150.00	150.00
Total Parts (S\$)					790.00	600.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	800.00	400.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	400.00	400.00
3	TO CONDUCT WHEEL ALIGNMENT TEST	New	120.00	0.00
Gross Labour Cost (\$)			1,320.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >