

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122004903/UQY3N2**Date:** 06/06/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SDA5595P**Insured Vehicle No :** YP2038Z

Date of Loss: 23/05/2022

Nature of Claim:

TP

Claim No: CDMCG22000977

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDA5595P**

Make &amp; Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A)

Engine No: 1AZE105774

Reg. Date: 24/06/2008 (Man. Year: 2008)

Chassis No: MR053BK4107030941

Colour: Gold

Odometer: 521555 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,610.90	1,270.57	1,340.33	51.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	480.00	520.00	52.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,610.90</b>	<b>1,750.57</b>	<b>1,860.33</b>	<b>51.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
<b>(S\$)</b>	3,610.90	1,400.00	2,210.90	61.23
<b>+ GST 7.00/7.00% (S\$)</b>	252.76	98.00	154.76	61.23
<b>Nett Amount (S\$)</b>	<b>3,863.66</b>	<b>1,498.00</b>	<b>2,365.66</b>	<b>61.23</b>

INSPECTION

Date of Assignment: 24/05/2022

Date Inspected: 24/05/2022 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2022)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDA5595P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR N/S	Badly Dented/Bent	1,685.10 F	*1,428.10 FL
2	1		*REAR DOOR OUTER HANDLE N/S	Serviceable	299.50 F	*- FL
3	1		*REAR DOOR OUTER PROTECTOR N/S	Necessary	366.10 F	*266.00 FL
4	1		*REAR DOOR HINGE N/S	Serviceable	105.10 F	*- FL
5	1		*REAR DOOR CHECKER N/S	Serviceable	155.10 F	*- FL
						F=Franchise part. L=ListItemDisc.
Sub Total (S\$)					2,610.90	1,694.10
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	423.53
Total Parts (S\$)					2,610.90	1,270.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	0.00
2	TO SPRAY RUST PROOFING	New	50.00	30.00
3	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	400.00	200.00
4	TO PUTTY & SPRAY PAINTING	New	500.00	250.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,000.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >