

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004907/KQY3M4**Date:** 22/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00011102100

Claimant Vehicle No : GBG2866U **Insured Vehicle No :** SMJ7594A

Date of Loss: 23/05/2022 Nature of Claim: TP Claim No: SNM22D203574/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG2866U**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2713556

Reg. Date: 10/07/2017 (Man. Year: 2017) Chassis No: JTFAT35Y70K208254

Colour: White Odometer: 79685 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)

Front Left Side: Bridgestone 9 mm Rear Left Side: Yokohama 9/9 mm

Front Right Side: Bridgestone 9 mm Rear Right Side: Yokohama 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	105.00	105.00	0.00	0.00
Miscellaneous Items	90.00	90.00	0.00	0.00
Labour	84.00	75.60	8.40	10.00
Paintwork Labour	200.00	180.00	20.00	10.00
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	479.00	450.60	28.40	5.93
+ GST 7.00/7.00% (\$\$)	33.53	31.54	1.99	5.93
Nett Amount (\$\$)	512.53	482.14	30.39	5.93

INSPECTION

Date of Assignment: 24/05/2022 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

Date Inspected: 16/06/2022 Inspected At: 160 SIN MING DRIVE #04-01, SIN MING
AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jun 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG2866U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Supplementary #1						
1	1		*L/R LAMP ASSY	Cracked	105.00 F	*105.00 F
F=Franchise part.						
Total Parts (S\$)					105.00	105.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Miscellaneous (REAR NUMBER PLATE, BLACK/WHITE TAPE 1.2M, BLACK/YELLOW TAPE 1.5M)	90.00	90.00
Sub Total (\$\$)			90.00	90.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Including Material (SAFETY BAR + LH T-LAMP PNL)	New	200.00	180.00
Labour Items				
2	Total of Labour PANEL / MECHANICAL LABOUR (R + R LEFT TAIL LAMP & L/TAILLAMP PANEL REPAIR)	New	84.00	75.60
Gross Labour Cost (\$\$)			284.00	255.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >