



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 2504E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BONNET (WCP)	BENT	680.00	680.00
1	FRT BONNET HINGE LH (WCP)	NOT NECESSARY	65.00	-
1	FRT BONNET MECHANISM LOCK (WCP)	NOT NECESSARY	150.00	-
1	FRT FENDER LH (WCP)	BENT	390.00	390.00
1	FRT FENDER INNER PANEL LH (WCP)	TO REPAIR SEE LABOUR	1,200.00	-
1	FRT FENDER INNER LINER LH (WCP)	DEFORMED	120.00	120.00
1	FRT BUMPER ASSY (WCP)	TORN	650.00	650.00
1	FRT BUMPER SIDE HOLDER LH (WCP)	DEFORMED	28.00	28.00
1	FRT BUMPER BRACKET LH (WCP)	NOT NECESSARY	30.00	-
1	FRT BUMPER INNER SPONGE (WCP)	CRACKED	120.00	120.00
1	FRT BUMPER REINFORCEMENT (WCP)	BENT	350.00	350.00
1	FRT BUMPER FOGLAMP LH (WCP)	CRACKED	150.00	150.00
1	FRT BUMPER FOGLAMP GARNISH LH (WCP)	DEFORMED	125.00	125.00
1	FRT BUMPER SIGNAL LAMP LH (WCP)	CUT	95.00	95.00
1	FRT BUMPER LOWER CENTRE AIR GRILLE (WCP)	CUT	170.00	170.00
1	FRT GRILLE ASSY (WCP)	CUT	200.00	200.00
1	HEADLAMP ASSY LH (WCP)	CRACKED	490.00	490.00
1	HEADLAMP PANEL LH (WCP)	BENT	110.00	110.00
1	HORN (WCP)	NOT NECESSARY	70.00	-
	COST PLUS 10%		519.30	367.80
			5,712.30	4,045.80
<u>SPECIAL NETT ITEMS</u>				
1	SET FRT FENDER INNER LINER CLIPS (SN)	NECESSARY	30.00	20.00
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			60.00	50.00
<u>LABOUR</u>				
	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING.		150.00	30.00

Report Ref No. CS6/AIS22004909/Tty3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT FENDER INNER PANEL LH.		800.00	600.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		800.00	700.00
			1,750.00	1,330.00
GRAND TOTAL			7,522.30	5,425.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00
LESS EXCESS			-1,000.00
NETT LIABILITY			2,800.00

Report Ref No. CS6/AIS22004909/Tty3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.