

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------------|---|--|------------------|-------|-------------------------|--|
| | SOMPO INSURAN | CE SINGAPORE PL | | Ref: | CS3/SMO22004912/Avy3m4 | |
| | 50 RAFFLES PLAC SINGAPORE LAND | CE #03-03 D TOWERSINGAPORE 048623 | | Date: | 20/06/2022 | |
| | | | | Code: | SMO | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SGL 990X | Veh. Inspected | | SGH 7770P | |
| | Policy No. | D22MTPV01005516 | Coverage (\$) | | 0.00 | |
| | Claim No. | CMTD2201786/GPL | Excess (\$) | | 0.00 | |
| | Assign From | GRACE TEO | Assign Date | | 25/05/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HONDA VEZEL HYBRID | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2015 | |
| | Chassis No. | RU11102193 | Colour | | BLUE | |
| | Odometer | 217657 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/60 R16 | YOKOHAMA | | 6 mm | |
| | L/H Front Tyre | 215/60 R16 | YOKOHAMA | | 6 mm | |
| | R/H Rear Tyre | 215/60 R16 | YOKOHAMA | | 6 mm | |
| | L/H Rear Tyre | 215/60 R16 | YOKOHAMA | | 6 mm | |
| 4. | 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 23/05/2022 | Inspect Date / 1 | Time | 25/05/2022 (04:19 PM) | |
| | Survey held at | V-TECH AUTO SERVICE | | | | |
| | | No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605 | | | | |
| 5a. | Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500 | | | | | |
| 5b. Estimate Days of Repair | | | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days | | | | |

Report Ref No. CS3/SMO22004912/Avy3m4

Inspected By

ADRIAN LING WAI PING

Licensed Appraiser

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.