

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004917/KNY3Q2**Date:** 03/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00144822101		
<b>Claimant Vehicle No :</b>	SLX2907C	<b>Insured Vehicle No :</b>	SBU64G		
Date of Loss:	19/05/2022	Nature of Claim:	TP	Claim No:	SNM22D203568

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLX2907C</b>		Engine No:	65492080035915
Make & Model:	MERCEDES-BENZ E220, 2.0 (A)		Chassis No:	WDD2130042A069648
Reg. Date:	13/02/2017 (Man. Year: 2016)		Odometer:	89891 km
Colour:	Metallic Silver			
Engine Capacity:	1950 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,841.10	2,029.50	2,811.60	58.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	530.00	590.00	52.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,961.10</b>	<b>2,559.50</b>	<b>3,401.60</b>	<b>57.06</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	417.28	179.17	238.11	57.06
<b>Nett Amount (\$\$)</b>	<b>6,378.38</b>	<b>2,738.67</b>	<b>3,639.71</b>	<b>57.06</b>

**INSPECTION**

Date of Assignment:	25/05/2022	
Date Inspected:	30/05/2022 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
Parts:	143	MERCEDES-BENZ E220 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX2907C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER +TOW COVER	Buckled	1,950.00 FL	*1,950.00 FL
2	1		*REAR BUMPER REFLECTOR RH	Serviceable	33.00 FL	*- FL
3	1		*REAR BUMPER LOWER GARNISH	Cracked	305.00 FL	*305.00 FL
4	1		*REAR BUMPER LOWER GARNISH CHROME MLDG CTR	Serviceable	330.00 FL	*- FL
5	1		*REAR BUMPER LOWER GARNISH CHROME MLDG RH	Serviceable	160.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	890.00 FL	*- FL
7	1		*REAR BUMPER BASIC CARRIER CTR	Serviceable	128.00 FL	*- FL
8	2		*REAR BUMPER BASIC CARRIER UPPER LH & RH	Serviceable	66.00 FL	*- FL
9	2		*REAR BUMPER BASIC CARRIER LOWER LH & RH	Serviceable	150.00 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	184.00 FL	*- FL
11	15		*REAR BUMPER RIVET	Not Necessary	105.00 FL	*- FL
12	2		*REVERSE SENSOR CTR LH & RH	Serviceable	560.00 FL	*- FL
13	4		*REVERSE SENSOR RING	Not Necessary	28.00 FL	*- FL
14	1		*REVERSE SENSOR WIRE HARNESS	Serviceable	490.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,379.00	2,255.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	537.90	225.50
Total Parts (\$\$)	4,841.10	2,029.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	60.00
2	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	500.00	220.00
4	TO SPRAY REAR BUMPER ,REAR END PANEL	New	500.00	250.00
<b>Gross Labour Cost (\$)</b>			<b>1,120.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >