

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004919/BVY3M4**Date:** 16/06/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00185262104

**Claimant Vehicle No :** SNB1078T **Insured Vehicle No :** SKG8810J

Date of Loss: 19/05/2022 Nature of Claim: TP Claim No: SNM22D203499/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB1078T**

Make & Model: HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A) Engine No: G4FMMU048243

Reg. Date: 30/07/2021 (Man. Year: 2021) Chassis No: KMHLN41ETNU213297

Colour: Silver Odometer: 5310 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,843.36	1,588.72	10,254.64	86.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	1,060.00	3,170.00	74.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,073.36</b>	<b>2,648.72</b>	<b>13,424.64</b>	<b>83.52</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,100.00</b>		
<b>(\$\$)</b>	16,073.36	2,100.00	13,973.36	86.93
<b>+ GST 7.00/7.00% (\$\$)</b>	1,125.14	147.00	978.14	86.93
<b>Nett Amount (\$\$)</b>	<b>17,198.50</b>	<b>2,247.00</b>	<b>14,951.50</b>	<b>86.93</b>

INSPECTION

Date of Assignment: 25/05/2022

Date Inspected: 30/05/2022 Inspected At: TEAM AUTOPRO PTE LTD (SIN MING) (HQ)  
160 SIN MING DRIVE, #01-14 SIN MING  
AUTOCITY  
SINGAPORE 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** Lim Teow Guan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 16 Jun 2022)

**Parts:** 143      HYUNDAI CN7 AVANTE 1.6 DOHC CVT S (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNB1078T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,782.40 FL	*- FL
2	1		*BOOTLID LOGO	Necessary	154.70 FL	*78.90 FL
3	1		*BOOTLID EMBLEM AVANTE	Necessary	102.00 FL	*70.50 FL
4	1		*BOOTLID EMBLEM S	Necessary	89.00 FL	*53.60 FL
5	1		*BOOTLID OUTER GARNISH	Not Damaged	352.00 FL	*- FL
6	1		*BOOTLID INNER TRIM BOARD	Not Damaged	158.10 FL	*- FL
7	1		*BOOTLID CENTER LAMP	Not Damaged	943.00 FL	*- FL
8	2		*BOOTLID LAMP	Not Damaged	1,328.40 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Not Damaged	98.50 FL	*- FL
10	1		*REAR BUMPER	Dented	859.40 FL	*495.00 FL
11	1		*REAR BUMPER LOWER GARNISH	Broken	653.50 FL	*398.40 FL
12	1		*REAR BUMPER SIDE LOWER COVER RH	No such part	163.40 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	185.60 FL	*80.60 FL
14	1		*REAR BUMPER INNER SPONGE	No such part	235.40 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	494.80 FL	*294.40 FL
16	2		*REAR BUMPER REINFORCEMENT BRACKET	No such part	156.00 FL	*- FL
17	1		*REAR BUMPER REFLECTOR	O/s Broken	803.00 FL	*202.00 FL
18	5		*REAR BUMPER BRACKET	Not Damaged	393.00 FL	*- FL
19	2		*REAR BUMPER NUMBER PLATE LAMP	Not Damaged	65.20 FL	*- FL
20	2		*REAR BUMPER LAMP	Not Damaged	402.00 FL	*- FL
21	1		*REAR BUMPER LAMP WIRE HARNESS	Not Damaged	121.00 FL	*- FL
22	1		*REAR END PANEL	Not Damaged	454.60 FL	*- FL
23	1		*REAR END PANEL TOP GARNISH	Not Damaged	68.20 FL	*- FL
24	2		*TAILLAMP	Not Damaged	2,108.00 FL	*- FL
25	2		*TAILLAMP LOWER BRACKET	Not Damaged	208.00 FL	*- FL
26	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
27	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
28	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
29	2		*BOOTLID LAMP SEAL	Not Damaged	120.00 FS	*- FS
30	2		*BOOTLID LAMP CLIPS	Not Damaged	100.00 FS	*- FS
31	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
32	1		*REAR BUMPER LOWER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
33	1		*REAR BUMPER SIDE LOWER COVER CLIPS	No such part	50.00 FS	*- FS
34	2		*REAR BUMPER REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
35	1		*REAR END PANEL SEALANT	Not Damaged	100.00 FS	*- FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Not Damaged	50.00 FS	*- FS
37	1		*TAILLAMP SEAL	Not Damaged	60.00 FS	*- FS
38	1		*TAILLAMP CLIPS	Not Damaged	50.00 FS	*- FS
39	2		*REVERSE SENSOR	Repeated	500.00 FS	*- FS
40	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,319.20</b>	<b>1,923.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,475.84	334.68
<b>Total Parts (\$\$)</b>	<b>11,843.36</b>	<b>1,588.72</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R BOOTLID COMPONENT	New	150.00	0.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	UPHOLSTERY	New	300.00	0.00
4	CHECK WIRING	New	100.00	0.00
5	CONDUCT WATER LEAK TEST	New	180.00	0.00
6	PANEL BEATING	New	1,600.00	600.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,600.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>4,230.00</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >