

TP Sampo SMN8069Y 2015 March.
 Veron Mazda 6 2488cc.
 Auto United JM6GJ1031F0147155

Front Bumper	Deformed	1151-30	✓
Front Bumper Clips	new	30(SN)	✓
Front Bumper Side Holder LH.	Deformed	45-40	✓
Front Bumper Fog Lamp LH.	2 new new	325-50	✓
Front Bumper Fog Lamp Cover LH.		65-10.	✓
Front Bumper Reinforcement	new new	552-40.	✓

~~Front Bumper Sponge~~

Front Bumper Sensor	new new	180-60	✓
Headlamp LH.	Cracked	3209-20	✓
Front LH Fender	Cracked	383-70	✓
Front LH Fender Inner Shield	Deformed	195-60	✓
Front LH Fender Inner Shield clips.	30(SN)		✓
	new		

6168.80

SMN 8069 Y.

Front LH Wheel Rem. Kit	1291.30	600(SN)
Front LH Tyre. New	300(SN)	X
Front LH Lower Arm. Best	246.90	✓
Front LH Shock Absorber	471.80	+
Front LH Knuckle Arm.	477.30	+
Front LH Wheel Hub c/w Bearing. Damaged	245.40	✓
Front LH Anti Roll Bar Linkage. AP on	116.20	X

3149

SMN 80694

Panel Beating

Spray Painting.

Wiring.

To spray tuft coat

To remove front bumper sensor

To dismantle front undercarriage.

To perform wheel alignment

~~800~~ 600

~~700~~ 400

~~50~~ 30

~~150~~ 30

~~100~~ 50

~~300~~ 150

~~150~~ 80

2250

11,567.80

List: 5477.50

Less 20%: 4382.

S.N: 860

Labour: 1340.

Total: 6382

L/S: 5.1K.

05 Days.

5.1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: