

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004922/KEA3Q2**Date:** 30/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210005853
Claimant Vehicle No :	SML8661Y	Insured Vehicle No :	SKB9143X
Date of Loss:	21/05/2022	Nature of Claim:	TP
		Claim No:	6272109440SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML8661Y	Engine No:	LEB7101461
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP72001026
Reg. Date:	07/06/2019 (Man. Year: 2018)	Odometer:	263916 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,503.20	22,248.36	6,254.84	21.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,870.00	3,880.00	2,990.00	43.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,373.20	26,128.36	9,244.84	26.14
Approved Total (Overridden) (S\$)		20,600.00		
(S\$)	35,373.20	20,600.00	14,773.20	41.76
+ GST 7.00/7.00% (S\$)	2,476.12	1,442.00	1,034.12	41.76
Nett Amount (S\$)	37,849.32	22,042.00	15,807.32	41.76
+ Car Rental (14.0 x S\$80.25/day) (S\$)		1,123.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		23,172.95		

INSPECTION

Date of Assignment:	24/05/2022	
Date Inspected:	24/05/2022	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	16.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	920.80 FL	*920.80 FL
2	2		*FRONT BONNET HINGE	Bent / Distorted	150.00 FL	*150.00 FL
3	1		*FRONT BONNET INNER CARDBOARD	Deformed	195.00 FL	*135.00 FL
4	8		*FRONT BONNET INNER CARDBOARD CLIP	Necessary	40.00 FL	*40.00 FL
5	1		*FRONT BONNET INNER RUBBER	Cut	158.90 FL	*158.90 FL
6	1		*FRONT BONNET INNER LOCK	Bent	195.50 FL	*158.00 FL
7	1		*FRONT BONNET INNER LOCK GARNISH	Distorted	55.90 FL	*55.90 FL
8	2		*FRONT HEADLAMP	O/S Cracked / N/S Mtg Cracked	5,100.00 FL	*4,500.00 FL
9	2		*FRONT HEADLAMP CHROME	O/S Cracked / N/S Scratched	311.00 FL	*311.00 FL
10	2		*FRONT HEADLAMP LOWER BRACKET	Cracked	116.00 FL	*116.00 FL
11	1		*FRONT CENTRE GRILLE BASE	Cracked	495.00 FL	*495.00 FL
12	1		*FRONT CENTRE GRILLE OUTER GARNISH	Cracked	325.50 FL	*325.50 FL
13	1		*FRONT CENTRE GRILLE H LOGO	Necessary	58.50 FL	*58.50 FL
14	1		*FRONT CENTRE GRILLE TOP GARNISH	Distorted	195.00 FL	*195.00 FL
15	8		*FRONT CENTRE GRILLE TOP GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
16	1		*FRONT CENTRE GRILLE LOWER CHROME	Distorted	215.00 FL	*215.00 FL
17	1		*FRONT BUMPER	Bent	1,150.50 FL	*1,050.00 FL
18	20		*FRONT BUMPER CLIP	Necessary (10 PCS ONLY)	100.00 FL	*50.00 FL
19	1		*FRONT BUMPER TOWING COVER	Missing	65.00 FL	*65.00 FL
20	2		*FRONT BUMPER SIDE RETAINER	Distorted	70.00 FL	*70.00 FL
21	1		*FRONT BUMPER REINFORCEMENT	Bent	420.90 FL	*420.90 FL
22	1		*FRONT BUMPER LOWER GRILLE	Distorted	158.60 FL	*158.60 FL
23	1		*FRONT BUMPER LOWER COVER	Deformed	255.20 FL	*255.20 FL
24	1		*FRONT BUMPER LOWER COVER RUBBER	Torn	185.00 FL	*185.00 FL
25	1		*FRONT BUMPER FOG LAMP	O/S Cracked	771.00 FL	*385.50 FL
26	1		*FRONT BUMPER FOG LAMP GARNISH	O/S Distorted	371.00 FL	*185.50 FL
27	2		*FRONT BUMPER FOG LAMP GARNISH TOP COVER	Serviceable	157.00 FL	*- FL
28	2		*FRONT FENDER	Buckled	1,197.00 FL	*990.00 FL
29	1		*FRONT FENDER INNER SHIELD	O/S Cracked	470.40 FL	*184.00 FL
30	20		*FRONT FENDER INNER SHIELD CLIP	Necessary (10 PCS ONLY)	100.00 FL	*50.00 FL
31	1		*FRONT SUPPORT PANEL	Bent	760.40 FL	*760.40 FL
32	2		*FRONT SUPPORT PANEL SIDE GARNISH	Distorted / Cut	151.00 FL	*151.00 FL
33	1		*FRONT AIR-CON CONDENSOR	Bent	985.00 FL	*985.00 FL
34	1		*FRONT AIR-CON CONDENSOR PIPE 1	Dented	285.50 FL	*285.50 FL
35	1		*FRONT AIR-CON CONDENSOR PIPE 2	Dented	280.00 FL	*280.00 FL
36	1		*FRONT AIR-CON CONDENSOR COWLING	Cracked	290.50 FL	*181.00 FL
37	1		*FRONT AIR-CON CONDENSOR COWLING MOTOR	Jammed	325.00 FL	*325.00 FL
38	1		*FRONT AIR-CON CONDENSOR COWLING MOTOR FAN	Cracked	95.00 FL	*95.00 FL
39	1		*FRONT RADIATOR	Housing Cracked	955.20 FL	*955.20 FL
40	1		*FRONT RADIATOR TOP HOSE	Serviceable	85.00 FL	*- FL
41	1		*FRONT RADIATOR LOWER HOSE	Serviceable	95.00 FL	*- FL
42	1		*FRONT RADIATOR COWLING	Cracked	295.00 FL	*181.00 FL
43	1		*FRONT RADIATOR COWLING MOTOR	Jammed	350.00 FL	*350.00 FL
44	1		*FRONT RADIATOR COWLING MOTOR FAN	Cracked	90.50 FL	*90.50 FL
45	1		*FRONT RADIATOR SPARE TANK	Dented	85.50 FL	*85.50 FL
46	1		*FRONT RADIATOR THERMAL START	Serviceable	125.50 FL	*- FL
47	2		*FRONT WIPER	Serviceable	100.00 FL	*- FL
48	1		*FRONT WIPER GARNISH	Dented	350.20 FL	*282.10 FL
49	2		*FRONT WIPER GARNISH SIDE COVER	Missing	171.00 FL	*171.00 FL
50	2		*FRONT WIPER ARM	Serviceable	250.00 FL	*- FL
51	1		*FRONT WIPER TANK	Dented	95.50 FL	*95.50 FL
52	1		*FRONT MANIFOLD	Cracked	950.50 FL	*950.50 FL

Report was unsubmitted during this print-out.

8/30/22, 2:44 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*FRONT ENGINE MOUNTING RH	Serviceable	485.50 FL	*- FL
54	1		*FRONT ENGINE MOUNTING LH	Serviceable	385.00 FL	*- FL
55	2		*FRONT SEAT BELT	Jammed	1,900.00 FL	*1,500.00 FL
56	1		*FRONT DASHBOARD	Torn	2,850.50 FL	*2,152.00 FL
57	1		*FRONT DASHBOARD AIR BAG	Burst	980.00 FL	*980.00 FL
58	1		*FRONT STEERING AIR BAG	Burst	1,200.00 FL	*1,200.00 FL
59	1		*AIR BAG CONTROL UNIT	Necessary	1,350.00 FL	*1,250.00 FL
60	2		*SIDE SKIRT	Serviceable	1,370.00 FL	*- FL
61	1		*SET FRONT NUMBER PLATE & CASING	Missing	50.00 FS	*45.00 FS
62	1		*SEALANT	Not Necessary	160.00 FS	*- FS
63	1		*HYBRID WATER PUMP	Cracked	780.50 FL	*623.70 FL
64	1		*HYBRID AIR-CON COMPRESER	Housing Cracked	2,850.00 FL	*1,900.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					35,576.50	27,799.20
- List Item Discount on L Items 20.00/20.00% (\$\$)					7,073.30	5,550.84
Total Parts (\$\$)					28,503.20	22,248.36
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	100.00	50.00
2	REMOVE & REFIT AIR-CON & RADIATOR	New	180.00	150.00
3	REMOVE & REFIT DASHBOARD	New	280.00	250.00
4	REMOVE & REFIT AIR BAG SYSTEM	New	380.00	250.00
5	REPROGRAMMING ECU & AIR BAG SYSTEM	New	380.00	220.00
6	WIRING	New	250.00	40.00
7	TUFFKOTE	New	300.00	120.00
8	SPRAY PAINTING	New	2,500.00	1,600.00
9	LABOUR CHARGES	New	2,500.00	1,200.00
Gross Labour Cost (\$)			6,870.00	3,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >