

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22004923/UPA3Q2**Date:** 20/03/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0000974
Claimant Vehicle No :	SKS8950A	Insured Vehicle No :	SLL1732J
Date of Loss:	24/05/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0002733

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS8950A		
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 HL HID 1634G5 (A)	Engine No:	CAXF19238
Reg. Date:	13/05/2015 (Man. Year: 2014)	Chassis No:	WVWZZZ16ZFM001618
Colour:	White	Odometer:	162469 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,858.90	3,634.58	16,224.32	81.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,510.00	2,530.00	62.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,898.90	5,144.58	18,754.32	78.47
Approved Total (Overridden) (\$\$)		4,100.00		
Nett Amount (\$\$)	23,898.90	4,100.00	19,798.90	82.84
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,407.45		

INSPECTION

Date of Assignment:	25/05/2022	
Date Inspected:	25/05/2022 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2022)
Parts:	143	VOLKSWAGEN JETTA GP 1.4 TSI 90 HL HID 1634G5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS8950A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,980.70 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	158.00 F	*- FL
3	1		*BOOTLID TSI EMBLEM	Necessary	62.00 F	*62.00 FL
4	1		*BOOTLID JETTA EMBLEM	Necessary	142.00 F	*75.00 FL
5	2		*BOOTLID REFLECTORS	Not Necessary	1,380.00 F	*- FL
6	1		*BOOTLID INNER TRIM	Not Necessary	331.00 F	*- FL
7	1		*BOOTLID INNER LOCK	Not Necessary	366.80 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	385.50 F	*293.00 FL
9	1		*REAR BUMPER	Distorted	2,245.20 F	*1,366.35 FL
10	1		*REAR BUMPER BEAM	Bent	844.50 F	*606.00 FL
11	1		*REAR BUMPER SPONGE	Torn	112.00 F	*95.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Necessary	190.00 F	*190.00 FL
13	1		*REAR BUMPER REFLECTORS	N/S Broken / O/S Not Necessary	170.00 F	*75.00 FL
14	4		*REAR BUMPER PDC SENSORS	Shorted	900.00 FS	*200.00 FS
15	1		*REAR BUMPER INNER TOP RETAINER	Cracked	231.00 F	*151.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	80.00 F	*50.00 FL
17	1		*REAR BUMPER LOWER GARNISH	Deformed	210.00 F	*210.00 FL
18	1		*REAR END PANEL	Repair	1,215.00 F	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	486.90 F	*- FL
20	1		*REAR FENDER FLOOR PANEL	Not Necessary	955.10 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	627.20 F	*- FL
22	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	568.00 F	*- FL
23	1		*TAILLAMPS	N/S Cracked	1,960.00 F	*442.00 FL
24	2		*TAILLAMP LOWER BRACKETS	No such part	216.00 F	*- FL
25	1		*REAR EXHAUST	Not Necessary	2,666.00 F	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	276.00 F	*- FL
27	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
28	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,858.90	3,815.35
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	180.77
Total Parts (\$)	19,858.90	3,634.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACE REAR REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	80.00	0.00
6	TO RESET & DIAGNOSIS REPROGRAMME SYSTEM	New	380.00	50.00
7	TO SPRAY RUST PROOFING	New	150.00	30.00
8	TO DISMANTLE & REFIX FUEL TANK	New	80.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	680.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	600.00
Gross Labour Cost (S\$)			4,040.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >