

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004931/BVY3Q2
Date: 27/10/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00050672200
Claimant Vehicle No :	PC4179L	Insured Vehicle No :	GBL3085Z
Date of Loss:	23/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203605/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC4179L	Engine No:	1KD2554445
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2230025484
Reg. Date:	18/12/2015 (Man. Year: 2015)	Odometer:	426166 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	DURATURN 5 mm	Rear Left Side:	DURATURN 5 mm
Front Right Side:	DURATURN 5 mm	Rear Right Side:	DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,210.67	9,435.02	15,775.65	62.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,830.00	2,890.00	3,940.00	57.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,040.67	12,325.02	19,715.65	61.53
Approved Total (Overridden) (S\$)		9,500.00		
Nett Amount (S\$)	32,040.67	9,500.00	22,540.67	70.35

INSPECTION

Date of Assignment:	25/05/2022	
Date Inspected:	26/05/2022	Inspected At:
Estimated Period of Repair:	12.0 days	Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity Singapore 575722

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Oct 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC4179L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,854.60 FL	*2,000.00 FL
2	1		*TAILGATE LOGO	Necessary	80.00 FL	*68.00 FL
3	1		*TAILGATE EMBLEM HIACE	Necessary	79.00 FL	*65.00 FL
4	1		*TAILGATE EMBLEM GL	Necessary	72.30 FL	*24.00 FL
5	1		*TAILGATE OUTER HANDLE GARNISH	Broken	364.70 FL	*200.00 FL
6	2		*TAILGATE NUMBER PLATE LAMP	Not Damaged	249.00 FL	*- FL
7	1		*TAILGATE INNER TRIMBOARD	Not Damaged	472.60 FL	*- FL
8	1		*TAILGATE INNER LOCK	Jammed	285.00 FL	*240.00 FL
9	1		*TAILGATE LOWER LOCK	Not Damaged	45.00 FL	*- FL
10	1		*TAILGATE OUTER KEY LOCK	Not Damaged	398.40 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Torn	379.10 FL	*300.00 FL
12	1		*TAILGATE WEATHERSTRIP PROTECTOR	Broken	194.00 FL	*194.00 FL
13	1		*TAILGATE WEATHERSTRIP MOULDING	No such part	185.20 FL	*- FL
14	1		*REAR BUMPER	Dented	679.00 FL	*460.00 FL
15	4		*REAR BUMPER LOWER BRACKET	Bent	312.80 FL	*300.00 FL
16	1		*REAR BUMPER STEP PANEL	Not Damaged	457.00 FL	*- FL
17	1		*REAR END PANEL (INNER)	Not Damaged	1,140.00 FL	*- FL
18	1		*REAR END PANEL (OUTER)	Dented	597.00 FL	*597.00 FL
19	1		*REAR FLOOR PANEL	Dented	1,960.00 FL	*1,280.00 FL
20	1		*REAR FLOOR PANEL MAT	Not Necessary	1,591.50 FL	*- FL
21	1		*REAR SPARE TYRE BRACKET	Not Damaged	587.40 FL	*- FL
22	1		*REAR SPARE TYRE BRACKET BOLT	Not Damaged	106.30 FL	*- FL
23	2		*TAILLAMP	Broken	975.20 FL	*600.00 FL
24	2		*TAILLAMP LOWER GARNISH	Broken	258.60 FL	*258.60 FL
25	2		*TAILLAMP LOWER GARNISH RETAINER	Necessary	130.00 FL	*130.00 FL
26	1		*BONNET	Repair	784.20 FL	*- FL
27	1		*BONNET LOGO	Necessary	80.00 FL	*68.00 FL
28	1		*BONNET LOCK	Not Damaged	95.80 FL	*- FL
29	1		*BONNET LOCK STICKER	No such part	55.80 FL	*- FL
30	2		*BONNET HINGE	Not Damaged	130.40 FL	*- FL
31	1		*FRONT BUMPER	Broken	634.50 FL	*634.50 FL
32	2		*FRONT BUMPER BRACKET	No such part	980.00 FL	*- FL
33	1		*FRONT BUMPER REINFORCEMENT	Bent	329.20 FL	*329.20 FL
34	1		*FRONT BUMPER GRILLE	Broken	948.30 FL	*270.00 FL
35	2		*FRONT BUMPER OUTER CHROME MOULDING	Broken	570.00 FL	*570.00 FL
36	1		*FRONT BUMPER LOWER GRILLE	Broken	471.00 FL	*471.00 FL
37	1		*FRONT BUMPER FOG LAMP COVER LH	Broken	110.00 FL	*110.00 FL
38	1		*FRONT CORNER PANEL LH	Broken	347.80 FL	*347.80 FL
39	1		*FRONT THIRD SIDE MIRROR LH	Broken	897.60 FL	*420.00 FL
40	1		*FRONT SUPPORT PANEL	No such part	1,384.20 FL	*- FL
41	1		*FRONT SUPPORT PANEL TOP COVER	Not Damaged	187.40 FL	*- FL
42	1		*FRONT SUPPORT PANEL TOP COVER RUBBER	Not Damaged	132.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*HEADLAMP LH	Broken	1,854.30 FL	*1,200.00 FL
44	1		*HEADLAMP LOWER BRACKET LH	No such part	278.00 FL	*- FL
45	1		*RADIATOR	Not Damaged	2,007.50 FL	*- FL
46	1		*A/C CONDENSER	Not Damaged	1,430.50 FL	*- FL
47	1		*INTERCOOLER	Not Damaged	1,108.60 FL	*- FL
48	1		*WIPER WASHER TANK	Not Damaged	324.70 FL	*- FL
49	1		*RADIATOR SPARE TANK	Not Damaged	295.80 FL	*- FL
50	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
51	1		*TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
52	1		*TAILGATE OUTER HANDLE GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
53	1		*TAILGATE INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*20.00 FS
54	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	120.00 FS	*40.00 FS
55	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	No such part	60.00 FS	*- FS
56	1		*TAILGATE STICKER 70KM/H	Necessary	40.00 FS	*20.00 FS
57	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
58	2		*REAR BUMPER SIDE RETAINER	Necessary	130.60 FS	*130.60 FS
59	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
60	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
61	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*40.00 FS
62	2		*TAILLAMP SEAL	Necessary	120.00 FS	*40.00 FS
63	2		*TAILLAMP LOWER GARNISH CLIPS	No such part	100.00 FS	*- FS
64	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS
65	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
66	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
67	2		*FRONT BUMPER SIDE RETAINER	Necessary	391.60 FS	*391.60 FS
68	1		*FRONT BUMPER GRILLE CLIPS	No such part	50.00 FS	*- FS
69	1		*FRONT BUMPER LOWER GRILLE CLIPS	No such part	50.00 FS	*- FS
70	1		*FRONT SUPPORT PANEL SEALANT	Not Damaged	100.00 FS	*- FS
71	1		*FRONT SUPPORT PANEL TOP COVER CLIPS	Not Damaged	50.00 FS	*- FS
72	1		*FRONT NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS
73	1		*COOLANT	Not Necessary	120.00 FS	*- FS
74	1		*A/C FLUID	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	32,683.50	12,219.30
- List Item Discount on L Items 25.00/25.00% (S\$)	7,472.83	2,784.28
Total Parts (S\$)	25,210.67	9,435.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	150.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	120.00	60.00
4	REAR CHECK WIRING	New	100.00	30.00
5	REAR PANEL BEATING	New	1,600.00	1,000.00
6	REAR RUST PROOFING	New	200.00	0.00
7	REAR SPRAY PAINTING	New	1,600.00	600.00
8	R&R BONNET COMPONENT	New	150.00	0.00
9	R&R RADIATOR	New	150.00	0.00
10	R&R A/C CONDENSER	New	150.00	0.00
11	R&R WIPER WASHER TANK	New	80.00	0.00
12	R&R RADIATOR SPARE TANK	New	80.00	0.00
13	FRONT CHECK WIRING	New	100.00	0.00
14	FRONT PANEL BEATING	New	1,000.00	600.00
15	FRONT RUST PROFING	New	200.00	0.00
16	FRONT SPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (\$\$)			6,830.00	2,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >