

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22004941/KPA3Q2**Date:** 30/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210051338
<b>Claimant Vehicle No :</b>	GBH7399M	<b>Insured Vehicle No :</b>	SFX1777M
Date of Loss:	22/05/2022	Nature of Claim:	TP
		Claim No:	4988567269SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBH7399M</b>	Engine No:	1GD8303837
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Chassis No:	GDH2012001708
Reg. Date:	13/09/2018 (Man. Year: 2018)	Odometer:	103974 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,451.00	2,442.00	4,009.00	62.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,740.00	2,460.00	58.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,651.00</b>	<b>4,182.00</b>	<b>6,469.00</b>	<b>60.74</b>
<b>+ GST 7.00/7.00% (S\$)</b>	745.57	292.74	452.83	60.74
<b>Nett Amount (S\$)</b>	<b>11,396.57</b>	<b>4,474.74</b>	<b>6,921.83</b>	<b>60.74</b>
<b>+ Loss of Use (4.0 x S\$80.00/day) (S\$)</b>		320.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,796.74</b>		

INSPECTION

Date of Assignment:	29/06/2022	
Date Inspected:	29/06/2022	Inspected At: Goldbell Engineering Pte Ltd (Ang Mo Kio) Blk 5035 Ang Mo Kio Industrial Park 2,, #01-367 Singapore 569538
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	280.00 F	*- FL
2	1		*TAILGATE	Bent	1,950.00 F	*1,850.00 FL
3	1		*TAILGATE MOULDING	Serviceable	350.00 F	*- FL
4	1		*TAILGATE HINGE LH	Repair	65.00 F	*- FL
5	1		*TAILGATE HINGE RH	Repair	65.00 F	*- FL
6	1		*TAILGATE LOCK	Repair	235.00 F	*- FL
7	1		*TAILGATE CATCH	Repair	95.00 F	*- FL
8	1		*TAILGATE HANDLER	Serviceable	85.00 F	*- FL
9	1		*REAR EMBLEM -TOYOTA	Necessary	55.00 F	*55.00 FL
10	1		*REAR STICKER -HIACE	Necessary	45.00 F	*45.00 FL
11	1		*TAILLAMP LH	Cracked	255.00 F	*255.00 FL
12	1		*REAR BOTTOM FENDER LH	Serviceable	235.00 F	*- FL
13	1		*REAR BOTTOM FENDER RH	Serviceable	235.00 F	*- FL
14	1		*REAR BUMPER	Bent	320.00 F	*320.00 FL
15	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
16	1		*REAR END PANEL	Repair	1,450.00 F	*- FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
18	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
19	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
20	1		*8 PAX STICKER	Necessary	15.00 FS	*15.00 FS
21	1		*TAILGATE WEATHERSTRIP	Cut	240.00 F	*240.00 FL
22	1		*TAILGATE LOCK COVER	Cracked	65.00 F	*65.00 FL
23	1		*REAR BUMPER RETAINER LH	Cracked	36.00 F	*36.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					<b>Sub Total (\$\$)</b>	<b>6,451.00 3,166.00</b>
					<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00 724.00</b>
					<b>Total Parts (\$\$)</b>	<b>6,451.00 2,442.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REFIX & REPAIR AFFECTED DAMAGED PARTS INCLUDING KNOCK OUT ,WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	2,400.00	900.00
2	TO REMOVE AND REFIX REAR WINDSCREEN	New	200.00	120.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	200.00	20.00
4	TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ETC	New	1,400.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,200.00</b>	<b>1,740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >