



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

4182.00

Not Notified

Running B4 part

4 days

Page

1 / 3

ESTIMATE

Date : 28/06/2022
To : AIG ASIA PACIFIC INSURANCE PTE. LTD.
Attn. :
Office / Mobile :
Email Address :

Reg No : GBH7399M
Model : TOYOTA HIACE DX 2.8 AUTO
Chassis No : GDH2012001708
Engine No : 1GD8303837
Quotation No. : 159307
Ref. No. :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

D.O.A. : 22/05/2022
Policy No. : DMCVSNW00109842102
Claim Type : TP CLAIM - AIG
Workshop : ANG MO KIO

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR WINDSCREEN MOULDING	1	280.00	0	280.00	280.00 X
2		TAILGATE 1850	1	1,950.00	0	1,950.00	1,950.00 ✓
3		TAILGATE MOULDING	1	350.00	0	350.00	350.00 X
4		TAILGATE HINGE LH	1	65.00	0	65.00	65.00 X
5		TAILGATE HINGE RH	1	65.00	0	65.00	65.00 X
6		TAILGATE LOCK	1	235.00	0	235.00	235.00 X
7		TAILGATE CATCH	1	95.00	0	95.00	95.00 X
8		TAILGATE HANDLER	1	85.00	0	85.00	85.00 X
9		REAR EMBLEM - TOYOTA	1	55.00	0	55.00	55.00 —
10		REAR STICKER - HIACE	1	45.00	0	45.00	45.00 —
11		TAILALMP LH	1	255.00	0	255.00	255.00 ✓
12		REAR BOTTOM FENDER LH	1	235.00	0	235.00	235.00 X
13		REAR BOTTOM FENDER RH	1	235.00	0	235.00	235.00 X
14		REAR BUMPER	1	320.00	0	320.00	320.00 —
15		REAR BUMPER CLIPS	1	30.00	0	30.00	30.00 —
16		REAR END PANEL	1	1,450.00	0	1,450.00	1,450.00 X

251

PARTS TOTAL :

5,750.00

SPECIAL NETT ITEMS

1	REAR WINDSCREEN SEALANT	1
2	REVERSE SENSOR	1
3	70 KM/H STICKER	1
4	8 PAX STICKER	1

80.00
250.00
15.00
15.00

PARTS TOTAL:

360.00

LKK Auto Consultants hence notify the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

biSAFE



FUSO

AIRMAN



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Page 2 / 3

ESTIMATE

Date	: 28/06/2022	Reg No	: GBH7399M
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA HIACE DX 2.8 AUTO
Attn.	:	Chassis No	: GDH2012001708
Office / Mobile	:	Engine No	: 1GD8303837
Email Address	:	Quotation No.	: 159307
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 22/05/2022
Attn.	: KONYINSIEW	Policy No.	: DMCVSNW00109842102
Office / Mobile	: +65 6861 0007	Claim Type	: TP CLAIM - AIG
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: ANG MO KIO

LABOUR CHARGES

1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	900h 2400.00 7
2	TO REMOVE AND REFIX REAR WINDSCREEN	120h 200.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING	200.00 20h
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	700h 1400.00

LABOUR TOTAL :	4,200.00
SUB-TOTAL :	10,310.00
GST @ 7% for \$ 10,310.00	721.70
GRAND TOTAL (S\$) :	11,031.70

FUSO

AIRMAN

bizSAFE
STAR

