

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22004942/APA3Q2**Date:** 25/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070148848
<b>Claimant Vehicle No :</b>	SKR5968A	<b>Insured Vehicle No :</b>	SMV9045S
Date of Loss:	21/05/2022	Nature of Claim:	TP
		Claim No:	6342969043SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKR5968A</b>		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B3516963
Reg. Date:	18/02/2015 (Man. Year: 2014)	Chassis No:	RU11016948
Colour:	White	Odometer:	119691 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,779.92	12,871.12	15,908.80	55.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,170.00	4,340.00	4,830.00	52.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>37,949.92</b>	<b>17,211.12</b>	<b>20,738.80</b>	<b>54.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>37,949.92</b>	<b>13,200.00</b>	<b>24,749.92</b>	<b>65.22</b>
<b>+ Loss of Use (14.0 x S\$60.00/day) (S\$)</b>		840.00		
<b>+ Doc/Search Fee (S\$)</b>		38.45		
<b>Nett Liability (S\$)</b>		<b>14,078.45</b>		

INSPECTION

Date of Assignment:	24/05/2022		
Date Inspected:	24/05/2022	Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	14.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**MARKET VALUE**

Market Value: \$40,000.00 (est) less LTA Rebate: \$20,931.00 (est) = Nett Value  
:\$19,069.00 (est)

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	927.50 FL	*765.00 FL
2	1		*FRONT BUMPER TOWING COVER	Not Necessary	21.00 FL	*- FL
3	1		*FRONT BUMPER LOWER LIP	Deformed	351.00 FL	*351.00 FL
4	2		*FRONT BUMPER FOGLAMP	Cracked	655.40 FL	*655.40 FL
5	2		*FRONT BUMPER FOGLAMP COVER	Deformed	98.00 FL	*98.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	189.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	46.00 FL	*23.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Dented	321.00 FL	*321.00 FL
9	1		*ENGINE UNDER CENTER COVER	Torn	589.10 FL	*317.00 FL
10	2		*FRONT WIPER PANEL SIDE GARNISH	Not Necessary	90.00 FL	*- FL
11	1		*FRONT WHEEL HOUSE PANEL	Repair	1,147.00 FL	*- FL
12	1		*FRONT WHEEL HOUSE PANEL SUPPORT PANEL	Buckled	674.00 FL	*485.00 FL
13	1		*FRONT FENDER LH	Distorted	580.00 FL	*580.00 FL
14	1		*FRONT FENDER INNER COWLING	N/S Torn	260.00 FL	*130.00 FL
15	1		*FRONT FENDER ARCD GARNISH	N/S Deformed	306.00 FL	*153.00 FL
16	1		*HEADLAMP(LED)	N/S Cracked	3,718.80 FL	*1,859.40 FL
17	2		*HEADLAMP LOWER BRACKET	Cracked	70.00 FL	*70.00 FL
18	2		*HEADLAMP SIDE BRACKET	Cracked	82.00 FL	*82.00 FL
19	1		*GRILLE CENTRE SUPPORT BRACKET	Not Necessary	49.00 FL	*- FL
20	1		*GRILLE LOGO	Necessary	28.00 FL	*28.00 FL
21	1		*GRILLE LOGO GARNISH	Not Necessary	289.00 FL	*- FL
22	1		*CENTRE GRILLE	Cracked	370.00 FL	*370.00 FL
23	2		*CENTRE GRILLE (CHROME)	Not Necessary	178.00 FL	*- FL
24	1		*BONNET	Dented	1,026.00 FL	*892.00 FL
25	1		*BONNET LOCK	Not Necessary	178.00 FL	*- FL
26	2		*BONNET INNER RUBBER (FRONT)	Not Necessary	54.00 FL	*- FL
27	1		*BONNET INNER RUBBER (SIDE)	N/S Cut	58.00 FL	*29.00 FL
28	1		*BONNET INSULATOR	Not Necessary	247.00 FL	*- FL
29	2		*BONNET STOPPER	Not Necessary	39.00 FL	*- FL
30	2		*BONNET HINGE	Not Necessary	90.00 FL	*- FL
31	1		*FRONT SUPPORT PANEL	Not Necessary	796.00 FL	*- FL
32	1		*FRONT SUPPORT PANEL TOP GARNISH	Torn	185.00 FL	*185.00 FL
33	1		*FUSE BOX	Not Necessary	257.00 FL	*- FL
34	2		*RADIATOR SIDE GARNISH	Necessary	136.00 FL	*136.00 FL
35	1		*AIR CON CONDENSER	Not Necessary	898.00 FL	*- FL
36	4		*AIR CON CONDENSER MOUNTING RUBBER	Not Necessary	112.00 FL	*- FL
37	1		*AIR CON PIPE (OUTLET)	Not Necessary	367.00 FL	*- FL
38	1		*AIR DUCT	Not Necessary	142.00 FL	*- FL
39	1		*AIR CLEANER RESONATOR	Cracked	360.00 FL	*360.00 FL
40	1		*AIR CLEANER RESONATOR DUCT	Not Necessary	150.00 FL	*- FL
41	1		*FRONT TEMPERATURE SENSOR	Not Necessary	142.00 FL	*- FL
42	1		*HORN	Not Necessary	105.00 FL	*- FL
43	1		*FRONT CHASSIS MEMBER LH	Repair	755.00 FL	*- FL
44	1		*REAR FENDER INNER TRIM	O/S Cracked	798.20 FL	*305.00 FL
45	2		*REAR FENDER COWLING	Not Necessary	300.40 FL	*- FL
46	2		*REAR FENDER ARCED GARNISH	Not Necessary	369.40 FL	*- FL
47	1		*REAR BUMPER	Distorted	865.50 FL	*865.50 FL
48	2		*REAR BUMPER REFLECTOR	Not Necessary	302.20 FL	*- FL
49	2		*REAR BUMPER SIDE	Deformed	460.00 FL	*390.00 FL
50	2		*REAR BUMPER SIDE RETAINER	Necessary	114.00 FL	*114.00 FL
51	2		*TAIL LAMP	Cracked	950.00 FL	*950.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		<b>*TAILGATE</b>	Distorted	1,420.00 FL	*1,100.00 FL
53	2		<b>*TAILGATE SIDE LAMP</b>	Cracked	480.00 FL	*480.00 FL
54	2		<b>*TAILGATE DAMPER</b>	Not Necessary	372.00 FL	*- FL
55	1		<b>*TAILGATE INNER HOLDER</b>	Not Necessary	52.00 FL	*- FL
56	2		<b>*TAILGATE STOPPER</b>	Not Necessary	38.00 FL	*- FL
57	1		<b>*TAILGATE TOP LOCK</b>	Damaged	180.00 FL	*180.00 FL
58	1		<b>*TAILGATE LOWER LOCK</b>	Not Necessary	24.70 FL	*- FL
59	1		<b>*TAILGATE INNER TRIM</b>	Cracked	398.60 FL	*295.00 FL
60	1		<b>*TAILGATE LOCK CONNECTOR</b>	Cracked	379.00 FL	*119.00 FL
61	1		<b>*TAILGATE WEATHERSTRIP</b>	Cut	168.40 FL	*168.40 FL
62	1		<b>*SET TAILGATE WINDSCREEN MOULDING</b>	Necessary	164.00 FL	*164.00 FL
63	1		<b>*BUZZER</b>	Damaged	109.00 FL	*109.00 FL
64	1		<b>*REAR END PANEL</b>	Distorted	530.00 FL	*530.00 FL
65	1		<b>*REAR END PANEL TOP GARNISH</b>	Deformed	146.30 FL	*146.30 FL
66	1		<b>*REAR FLOOR PANEL</b>	Repair	1,130.00 FL	*- FL
67	1		<b>*REAR FLOOR TOWING PANEL</b>	Repair	545.00 FL	*- FL
68	1		<b>*REAR FLOOR PANEL BOTTOM GARNISH</b>	Deformed	269.00 FL	*269.00 FL
69	1		<b>*REAR FLOOR PANEL TOP BOARD</b>	Deformed	300.40 FL	*300.40 FL
70	1		<b>*REAR STORAGE BOX</b>	Deformed	495.00 FL	*268.00 FL
71	1		<b>*SET CENTER EXHAUST GASKET</b>	Not Necessary	80.00 FL	*- FL
72	1		<b>*CENTER EXHAUST</b>	Not Necessary	1,980.00 FL	*- FL
73	1		<b>*CENTER EXHAUST INSULATOR</b>	Not Necessary	180.00 FL	*- FL
74	1		<b>*REAR EXHAUST INSULATOR</b>	Not Necessary	155.00 FL	*- FL
75	1		<b>*REAR EXHAUST PIPE</b>	Bent	980.00 FL	*598.00 FL
76	4		<b>*REAR EXHAUST MOUNTING</b>	Not Necessary	72.00 FL	*- FL
77	1		<b>*SET REAR EXHAUST GASKET</b>	Necessary	80.00 FL	*35.00 FL
78	1		<b>*FRONT NUMBER PLATE</b>	Not Necessary	50.00 FS	*- FS
79	1		<b>*SET FRONT BUMPER CLIP</b>	Necessary	50.00 FS	*30.00 FS
80	1		<b>*SET FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP</b>	Not Necessary	50.00 FS	*- FS
81	1		<b>*SET ENGINE UNDER CENTER COVER CLIP</b>	Necessary	50.00 FS	*30.00 FS
82	1		<b>*SET FRONT FENDER COWLING CLIP</b>	Necessary	80.00 FS	*30.00 FS
83	1		<b>*SET FRONT FENDER ARCD GARNISH CLIP</b>	Necessary	60.00 FS	*20.00 FS
84	1		<b>*SET FRONT WIPER PANEL SIDE GARNISH CLIP</b>	Not Necessary	60.00 FS	*- FS
85	1		<b>*SET CENTRE GRILLE CLIP</b>	Necessary	30.00 FS	*20.00 FS
86	1		<b>*SET GRILLE LOGO GARNISH CLIP</b>	Not Necessary	50.00 FS	*- FS
87	1		<b>*SET FRONT BONNET INSULATOR CLIP</b>	Not Necessary	50.00 FS	*- FS
88	1		<b>*SET FRONT WIPER PANEL GARNISH CLIP</b>	Not Necessary	50.00 FS	*- FS
89	1		<b>*FRONT SUPPORT PANEL SEALANT</b>	Not Necessary	80.00 FS	*- FS
90	1		<b>*SET FRONT SUPPORT PANEL TOP GARNISH CLIP</b>	Necessary	50.00 FS	*20.00 FS
91	1		<b>*BATTERY</b>	Not Necessary	320.00 FS	*- FS
92	1		<b>*COOLANT</b>	Not Necessary	80.00 FS	*- FS
93	1		<b>*SET REAR BUMPER CLIPS</b>	Necessary	50.00 FS	*30.00 FS
94	1		<b>*TAILGATE SEALANT</b>	Not Necessary	80.00 FS	*- FS
95	1		<b>*SET TAILGATE OUTER GARNISH CLIP</b>	Not Necessary	50.00 FS	*- FS
96	1		<b>*SET TAILGATE INNER TRIM BOARD CLIP</b>	Necessary	50.00 FS	*30.00 FS
97	1		<b>*TAILGATE WINDSCREEN SEALANT</b>	Necessary	80.00 FS	*40.00 FS
98	1		<b>*TAILGATE WINDSCREEN INNER SEAL</b>	Necessary	60.00 FS	*30.00 FS
99	1		<b>*SET TAIL LAMP CLIP</b>	Necessary	40.00 FS	*40.00 FS
100	1		<b>*SET REAR FENDER INNER TRIM CLIP</b>	Necessary	60.00 FS	*30.00 FS
101	1		<b>*SET REAR FENDER COWLING CLIP</b>	Not Necessary	60.00 FS	*- FS
102	1		<b>*SET REAR FENDER ARCD GARNISH CLIP</b>	Not Necessary	60.00 FS	*- FS
103	1		<b>*SET REAR END PANEL TOP GARNISH CLIP</b>	Necessary	50.00 FS	*10.00 FS
104	1		<b>*REAR END PANEL INSULATION SEAL</b>	Necessary	150.00 FS	*60.00 FS
105	1		<b>*REAR FLOOR PANEL SEALANT</b>	Not Necessary	350.00 FS	*- FS
106	1		<b>*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP</b>	Necessary	60.00 FS	*30.00 FS
107	1		<b>*REAR FLOOR TOWING PANEL SEALANT</b>	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
108	1		<b>*REVERSE CAMERA</b>	Not Necessary	480.00 FS	*- FS	
109	2		<b>*REVERSE SENSOR</b>	Damaged	220.00 FS	*200.00 FS	
					<b>Sub Total (\$)</b>	<b>35,184.90</b>	<b>15,926.40</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>6,404.98</b>	<b>3,055.28</b>
					<b>Total Parts (\$)</b>	<b>28,779.92</b>	<b>12,871.12</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	1,800.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	REMOVE AND REFIX WIREHARNES AND WIRING CHECKING	New	180.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
6	REFOCUS HEADLAMP BEAM	New	60.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
8	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	1,200.00
9	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	900.00
10	TUFF COAT	New	250.00	100.00
11	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
13	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
14	REMOVE AND REFIX VIDEO RECORDER	New	80.00	50.00
15	REAR CHASSIS ALIGNMENT	New	250.00	0.00
16	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
17	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
18	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
19	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
20	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	80.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>9,170.00</b>
				<b>4,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >