

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004943/VVY3M4**Date:** 25/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00089732102
Claimant Vehicle No :	SMR3609B	Insured Vehicle No :	GBD9557G
Date of Loss:	24/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203601/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3609B	Engine No:	PE20671526
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GJ1072G0213161
Reg. Date:	28/10/2015 (Man. Year: 2015)	Odometer:	257346 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,279.36	7,084.88	7,194.48	50.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	1,560.00	2,920.00	65.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,759.36	8,644.88	10,114.48	53.92
Approved Total (Overridden) (\$\$)		6,050.00		
Nett Amount (\$\$)	18,759.36	6,050.00	12,709.36	67.75

INSPECTION

Date of Assignment:	11/06/2022		
Date Inspected:	27/05/2022	Inspected At:	JEW Motors (HQ) 60 Jalan Lam Huat Carros Centre #03-72 Singapore 737869
Estimated Period of Repair:	5.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR3609B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,115.60 FL	*1,115.60 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	41.50 FL	*41.50 FL
3	1		*BOOTLID MAZDA 6 EMBLEM	Necessary	33.40 FL	*33.40 FL
4	1		*BOOTLID SKYACTIV EMBLEM	Necessary	66.70 FL	*66.70 FL
5	1		*BOOTLID CHROME MOULDING	Scratched	304.40 FL	*304.40 FL
6	1		*SET BOOTLID CHROME MOULDING CLIPS	Necessary	50.00 FL	*30.00 FL
7	1		*BOOTLID RH CHROME MOULDING	Serviceable	167.00 FL	*- FL
8	1		*BOOTLID RH CHROME MOULDING CLIPS	Serviceable	28.00 FL	*- FL
9	1		*BOOTLID LH CHROME MOULDING	Serviceable	167.00 FL	*- FL
10	1		*BOOTLID LH CHROME MOULDING CLIPS	Serviceable	28.00 FL	*- FL
11	1		*BOOTLID RH NUMBER PLATE LAMP	Serviceable	76.40 FL	*- FL
12	1		*BOOTLID LH NUMBER PLATE LAMP	Serviceable	76.40 FL	*- FL
13	1		*BOOTLID REVERSE CAMERA	Serviceable	1,019.00 FL	*- FL
14	1		*BOOTLID RH LAMP ASSY	Cracked	778.00 FL	*778.00 FL
15	1		*BOOTLID LH LAMP ASSY	Serviceable	778.00 FL	*- FL
16	1		*BOOTLID OPEN SWITCH	Serviceable	348.20 FL	*- FL
17	1		*BOOTLID LOCK	Jammed	178.40 FL	*178.40 FL
18	1		*BOOTLID LOCK CATCH	Serviceable	56.60 FL	*- FL
19	1		*BOOTLID RH HINGE	Serviceable	219.90 FL	*- FL
20	1		*BOOTLID LH HINGE	Serviceable	219.90 FL	*- FL
21	1		*BOOTLID INNER TRIM	Cut	191.00 FL	*191.00 FL
22	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	60.00 FL	*30.00 FL
23	1		*BOOTLID RH RUBBER STOPPER	Serviceable	33.50 FL	*- FL
24	1		*BOOTLID LH RUBBER STOPPER	Serviceable	33.50 FL	*- FL
25	1		*BOOTLID WEATHERSTRIP	Deformed	142.20 FL	*142.20 FL
26	1		*REAR BUMPER	Cut	1,266.60 FL	*1,266.60 FL
27	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*36.00 FL
28	1		*REAR BUMPER RH REFLECTOR	Cracked	61.20 FL	*61.20 FL
29	1		*REAR BUMPER LH REFLECTOR	Serviceable	61.20 FL	*- FL
30	1		*REAR BUMPER RH TOWING COVER	Serviceable	48.90 FL	*- FL
31	1		*REAR BUMPER LH TOWING COVER	Serviceable	48.90 FL	*- FL
32	1		*REAR BUMPER REINFORCEMENT	Dented	538.30 FL	*538.30 FL
33	1		*REAR BUMPER RH SIDE RETAINER	Necessary	45.00 FL	*45.00 FL
34	1		*REAR BUMPER LH SIDE RETAINER	Necessary	45.00 FL	*45.00 FL
35	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	22.00 FL	*- FL
36	1		*SET REAR BUMPER RIVETS	Not Necessary	28.00 FL	*- FL
37	1		*REAR BUMPER RH SPLASH SHIELD	Serviceable	55.60 FL	*- FL
38	1		*SET REAR BUMPER RH SPLASH SHIELD CLIPS	Serviceable	28.00 FL	*- FL
39	1		*REAR BUMPER LH SPLASH SHIELD	Serviceable	55.60 FL	*- FL
40	1		*SET REAR BUMPER LH SPLASH SHIELD CLIPS	Serviceable	28.00 FL	*- FL
41	4		*REAR BUMPER REVERSE SENSOR COVERS	Serviceable	72.80 FL	*- FL
42	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Serviceable	198.00 FL	*- FL
43	1		*RH TAILLAMP	Cracked	1,592.30 FL	*800.00 FL
44	1		*RH TAILLAMP GASKET	Necessary	27.70 FL	*27.70 FL
45	1		*LH TAILLAMP	Cracked	1,592.30 FL	*800.00 FL
46	1		*LH TAILLAMP GASKET	Necessary	27.70 FL	*27.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*END PANEL	Dented	606.70 FL	*606.70 FL
48	1		*END PANEL INNER GARNISH	Cut	159.00 FL	*159.00 FL
49	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	40.00 FL	*30.00 FL
50	1		*END PANEL ANTENNA SENSOR	Serviceable	93.00 FL	*- FL
51	1		*REAR FENDER RH INNER TRIM	Cut	521.70 FL	*521.70 FL
52	1		*SET REAR FENDER RH INNER TRIM CLIPS	Necessary	50.00 FL	*30.00 FL
53	1		*REAR FENDER LH INNER TRIM	Serviceable	521.70 FL	*- FL
54	1		*SET REAR FENDER LH INNER TRIM CLIPS	Serviceable	50.00 FL	*- FL
55	1		*REAR COMPARTMENT PANEL LH TRAY GARNISH	Serviceable	151.00 FL	*- FL
56	1		*REAR COMPARTMENT PANEL RH TRAY GARNISH	Serviceable	151.00 FL	*- FL
57	1		*REAR COMPARTMENT PANEL TOP COVER BOARD	Serviceable	540.70 FL	*- FL
58	1		*REAR COMPARTMENT PANEL TOP COVER BOARD MAT	Serviceable	309.10 FL	*- FL
59	1		*EXHAUST SILENCER	Serviceable	1,486.70 FL	*- FL
60	1		*EXHAUST SILENCER HEAT SHIELD	Serviceable	59.60 FL	*- FL
61	1		*EXHAUST SILENCER GASKET	Serviceable	25.60 FL	*- FL
62	2		*EXHAUST SILENCER RUBBER MOULDING	Serviceable	72.00 FL	*- FL
63	1		*REAR BUMPER RH SIDE REVERSE SENSOR}	Damaged	144.64 FS	*700.00 FS
64	1		*REAR BUMPER RH CENTRE REVERSE SENSOR}	Damaged	144.64 FS	*- FS
65	1		*REAR BUMPER LH CENTRE REVERSE SENSOR}	Damaged	144.64 FS	*- FS
66	1		*REAR BUMPER LH SIDE REVERSE SENSOR}	Damaged	144.64 FS	*- FS
67	1		*END PANEL JOINT SEAL	Necessary	80.00 FS	*60.00 FS
68	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,672.06	8,666.10
- List Item Discount on L Items 20.00/20.00% (\$)	3,392.70	1,581.22
Total Parts (\$)	14,279.36	7,084.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO PROVIDE WORKMANSHIP CUT / WELD AND REPLACING OF PARTS	New	1,800.00	700.00
2	SPRAY PAINT ON AFFECTED AND CONSISTENT AREAS	New	1,600.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	30.00
4	APPLY RUST CHEMICAL ON AFFECTED AREAS	New	120.00	30.00
5	REMOVE AND REPLACE BOOTLID REVERSE CAMERA	New	120.00	0.00
6	REMOVE AND REPLACE BOOTLID INNER MECHANISM	New	100.00	40.00
7	REMOVE AND REPLACE REAR INNER GARNISH AND TRIM	New	300.00	30.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	120.00	30.00
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET	New	220.00	0.00
Gross Labour Cost (\$\$)			4,480.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >