

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004946/BQY3E2**Date:** 06/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00149342101	
Claimant Vehicle No :	SLC6926G	Insured Vehicle No :	GBF5321K	
Date of Loss:	24/05/2022	Nature of Claim:	TP	Claim No: SNM22D203632/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC6926G		Engine No:	1ZRY278210
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)		Chassis No:	MR053REH104549017
Reg. Date:	24/05/2016 (Man. Year: 2016)		Odometer:	122089 km
Colour:	Grey			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,943.38	7,589.83	8,353.55	52.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	2,690.00	3,260.00	54.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,893.38	10,279.83	11,613.55	53.05
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	21,893.38	8,200.00	13,693.38	62.55
+ GST 8.00/8.00% (S\$)	1,751.47	656.00	1,095.47	62.55
Nett Amount (S\$)	23,644.85	8,856.00	14,788.85	62.55

INSPECTION

Date of Assignment:	25/05/2022		
Date Inspected:	26/05/2022	Inspected At:	Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	9.0 days		

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Feb 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC6926G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,093.00 FL	*891.00 FL
2	1		*BOOTLID LOGO	Necessary	85.50 FL	*85.50 FL
3	1		*BOOTLID EMBLEM COROLLA	Necessary	68.00 FL	*68.00 FL
4	1		*BOOTLID EMBLEM ALTIS	Necessary	65.37 FL	*65.37 FL
5	1		*BOOTLID OUTER CHROME GARNISH	Broken	274.80 FL	*274.80 FL
6	1		*BOOTLID NUMBER PLATE LAMP (2PCS)	Broken (1Pc Only)	191.00 FL	*95.50 FL
7	2		*BOOTLID LAMP	Broken	970.60 FL	*752.00 FL
8	1		*BOOTLID INNER LOCK	Jammed	298.70 FL	*298.70 FL
9	1		*BOOTLID INNER LOCK STRIKER	Not Damaged	65.00 FL	*- FL
10	1		*BOOTLID INNER TRIM BOARD	Not Damaged	352.80 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Torn	298.60 FL	*197.00 FL
12	2		*BOOTLID HINGE	Not Damaged	376.60 FL	*- FL
13	1		*BOOTLID ANTENNA SENSOR	Broken	218.40 FL	*218.40 FL
14	1		*REAR BUMPER	Broken	885.90 FL	*581.00 FL
15	1		*REAR BUMPER INNER SPONGE	No such part	141.80 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	487.30 FL	*399.00 FL
17	2		*REAR BUMPER SIDE BRACKET	Broken	171.20 FL	*171.20 FL
18	1		*REAR BUMPER REFLECTOR	O/S Broken	187.20 FL	*93.60 FL
19	2		*REAR BUMPER REVERSE SENSOR	Short Circuit	536.00 FL	*200.00 FL
20	1		*REAR END PANEL	Dented	762.10 FL	*655.00 FL
21	1		*REAR END PANEL TOP GARNISH	Broken	268.00 FL	*230.00 FL
22	1		*SPARE TYRE PANEL	Dented	837.70 FL	*837.70 FL
23	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	498.00 FL	*- FL
24	1		*SPARE TYRE PANEL INSULATOR	Necessary	234.00 FL	*150.00 FL
25	1		*REAR FENDER	O/S Bent	2,356.00 FL	*1,178.00 FL
26	2		*REAR FENDER INNER TRIM BOARD	Torn	1,378.00 FL	*910.00 FL
27	2		*REAR FENDER INNER COWLING	Not Damaged	248.00 FL	*- FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	266.70 FL	*138.00 FL
29	2		*REAR AIR VENTS	Not Damaged	124.60 FL	*- FL
30	1		*REAR CHASSIS RH	Not Damaged	928.70 FL	*- FL
31	2		*TAILLAMP	Broken	1,189.20 FL	*946.00 FL
32	2		*TAILLAMP LOWER BRACKET	Necessary	164.00 FL	*164.00 FL
33	2		*TAILLAMP BASE PANEL	Not Damaged	399.20 FL	*- FL
34	1		*EXHAUST PIPE	Not Necessary	891.00 FL	*- FL
35	2		*EXHAUST MOUNTING	Not Damaged	137.20 FL	*- FL
36	1		*EXHAUST HEAT SHIELD	Not Damaged	145.80 FL	*- FL
37	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
38	1		*BOOTLID SEALANT	Necessary	100.00 FS	*30.00 FS
39	2		*BOOTLID LAMP SEAL	Necessary	120.00 FS	*40.00 FS
40	2		*BOOTLID LAMP CLIPS	No such part	100.00 FS	*- FS
41	1		*BOOTLID OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*BOOTLID INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
43	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
44	2		*REAR BUMPER SIDE RETAINER	Not Necessary	236.40 FS	*- FS
45	2		*REAR BUMPER REVERSE SENSOR SEAL	Not Necessary	90.00 FS	*- FS
46	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
47	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
48	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
49	2		*REAR FENDER SEALANT	Necessary	200.00 FS	*20.00 FS
50	2		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*40.00 FS
51	2		*REAR FENDER INNER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
52	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
53	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
54	1		*REAR WINDSCREEN PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
55	2		*TAILLAMP SEAL	Necessary	120.00 FS	*40.00 FS
56	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*20.00 FS
57	2		*TAILLAMP BASE PANEL SEALANT	Not Necessary	200.00 FS	*- FS
58	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS
59	1		*REAR REVERSE CAMERA	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,342.37	9,989.77
- List Item Discount on L Items 25.00/25.00% (\$)	4,398.99	2,399.94
Total Parts (\$)	15,943.38	7,589.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	R&R REAR WINDSCREEN	New	250.00	120.00
4	R&R FUEL TANK PIPE	New	150.00	0.00
5	R&R EXHAUST PIPE	New	150.00	0.00
6	MOUNT WORK BENCH	New	350.00	0.00
7	CHASSIS ALIGNMENT	New	300.00	0.00
8	DIAGNOSTIC & RESET FAULT CODE	New	300.00	0.00
9	UPHOLSTERY	New	300.00	0.00
10	CHECK WIRING	New	100.00	30.00
11	PANEL BEATING	New	1,800.00	1,200.00
12	RUST PROOFING	New	200.00	0.00
13	SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			5,950.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >