

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22004952/KVY3E2

Date: 29/06/2022

REFERENCE

Insured/Claimant: CHIA TECK LEONG JIMMY Policy No: D18MPC0000192-03
Date of Loss: 22/05/2022 Nature of Claim: OD Claim No: MPC2022D0002715

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDU9191P**
Make & Model: BMW 730LI, 2.0 LED NAV HUD SR (A) Engine No: 26189659B48B20B
Reg. Date: 03/07/2017 (Man. Year: 2016) Chassis No: WBA7A02020GL97062
Colour: Metallic Silver Odometer: 38588 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$190,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R19 Rear Tyre Size: 275/40 R19
Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm
Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,657.59	7,338.80	4,318.79	37.05
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	3,350.00	2,480.00	870.00	25.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,018.59	9,829.80	5,188.79	34.55
+ GST 7.00/7.00% (S\$)	1,051.30	688.09	363.21	34.55
Nett Amount (S\$)	16,069.89	10,517.89	5,552.00	34.55

INSPECTION

Date of Assignment: 26/05/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected: 26/05/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2022)
Parts:	143	BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDU9191P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,974.75 F (5/0.00)%	*- F
2	1		*FRONT LH FENDER	Bent	1,304.95 F (5/0.00)%	*1,304.95 F (5/0.00)%
3	1		*FRONT LH FENDER EMBLEM M	Necessary	83.80 F (5/0.00)%	*83.80 F (5/0.00)%
4	1		*FRONT LH FENDER PROTECTOR	Serviceable	198.70 F (5/0.00)%	*- F
5	1		*FRONT LH DOOR	Bent	2,352.35 F (5/0.00)%	*2,352.35 F (5/0.00)%
6	1		*FRONT LH DOOR GARNISH	Necessary	238.55 F (5/0.00)%	*238.55 F (5/0.00)%
7	1		*FRONT LH DOOR WEATHER STRIP	Necessary	243.65 F (5/0.00)%	*243.65 F (5/0.00)%
8	1		*REAR LH DOOR	Bent	2,585.35 F (5/0.00)%	*2,585.35 F (5/0.00)%
9	1		*REAR LH DOOR GARNISH	Necessary	238.55 F (5/0.00)%	*238.55 F (5/0.00)%
10	1		*REAR LH DOOR WEATHER STRIP	Necessary	243.65 F (5/0.00)%	*243.65 F (5/0.00)%
11	1		*REAR BUMPER	Repair	2,365.45 F (5/0.00)%	*- F
12	1		*REVERSE SENSOR OUTER	Scratched	251.20 F (5/0.00)%	*251.20 F (5/0.00)%
13	1		*REVERSE SENSOR COVER	Serviceable	7.20 F (5/0.00)%	*- F
Supplementary #1						
14	1		*DOOR RUBBER/LH FRT DR	Necessary	91.50 F (5/0)%	*91.50 F (5/0)%
15	1		*DOOR RUBBER(LH REAR DR	Necessary	91.50 F (5/0.00)%	*91.50 F (5/0.00)%

F=Franchise part. (x/y)%=(PDisc/Depr)%.

Sub Total (\$)	12,271.15	7,725.05
- List Item Discount on L Items 0.00/0.00% (\$)	613.56	386.25
Total Parts (\$)	11,657.59	7,338.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ON LH FRONT BUMPER TO REAR BUMPER ,LH CENTRE PILLAR LH FENDER ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1,000.00	750.00
2	TO PUTTY,RESPRAY ON LH FRT BUMPER ,LH FENDER ,LH FRT DOOR,LH REAR DOOR,LH REAR FENDER AND REAR BUMPER	New	1,700.00	1,500.00
3	TRANSFER DOOR PARTS TO NEW 2 DOORS	New	300.00	200.00
4	CHECK LIGHTING AND WIRING	New	50.00	30.00
5	TO RESET ECU SYSTEM	New	300.00	0.00
Gross Labour Cost (\$\$)			3,350.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >