



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 7000G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRT BUMPER (CONSISTENT)	MTG CRACKED / DISTORTED	1,793.50	1,395.00
1	FR FENDER ARCH GARNISH RH (CONSISTENT)	DENTED	1,012.80	600.00
	LESS 10% DISCOUNT		-280.63	-199.50
			2,525.67	1,795.50
<b>SPECIAL NETT ITEMS</b>				
1	SET FRT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	55.00	55.00
1	SET FRT FENDER ARCH GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRT SPORT RIM RH (SN) (CONSISTENT)	SERVICEABLE	650.00	-
			740.00	90.00
<b>LABOUR</b>				
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS.		50.00	10.00
	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT.		500.00	250.00
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS.		500.00	400.00
	TO REMOVE & REFIT PDC SENSOR.		80.00	50.00
	RUST PROOFING ON AFFECTED PORTIONS.	NOT NECESSARY	100.00	-
			1,230.00	710.00
<b>GRAND TOTAL</b>			<b>4,495.67</b>	<b>2,595.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,050.00</b>

Report Ref No. CS/ASM22004953/Kvcm4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.