

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQI22004955/ENY3E2

Date: 03/08/2022

REFERENCE

Insured/Claimant: LEE BIOW CHONG JAY Policy No: DMPPHQ21-007131
Date of Loss: 01/05/2022 Nature of Claim: OD Claim No: DM22HO00687

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK4J**
Make & Model: FERRARI F8 TRIBUTO, 3.9 (A) Engine No: 506020
Reg. Date: 17/09/2021 (Man. Year: 2021) Chassis No: ZFF92LMC000268636
Colour: Grey Odometer: 2601 km
Engine Capacity: 3902 cc
Market Value/New Car Price: S\$1,298,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35Z R20 Rear Tyre Size: 245/35Z R20
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	167,962.01	127,243.89	40,718.12	24.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	87,300.00	59,040.00	28,260.00	32.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	255,262.01	186,283.89	68,978.12	27.02
- Excess (S\$)	25,000.00	25,000.00	0.00	0.00
(S\$)	230,262.01	161,283.89	68,978.12	29.96
+ GST 7.00/7.00% (S\$)	16,118.34	11,289.87	4,828.47	29.96
Nett Amount (S\$)	246,380.35	172,573.76	73,806.59	29.96

INSPECTION

Date of Assignment: 25/05/2022
Date Inspected: 26/05/2022 Inspected At: ITAL Auto Pte Ltd (HQ)
30 Leng Kee Road
Singapore 159100
Estimated Period of Repair: 30.0 days

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2022)
Parts: M1-COUCPE	FERRARI F8 TRIBUTO 3.9 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK4J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*LH WATER RADIATOR	Dented	3,812.16 F	*3,812.16 F
2	1	*FAN COWL	Not Necessary	1,693.89 F	*- F
3	1	*COMPL. LH FRONT HUB CARRIER	Necessary / Bent	4,861.18 F	*4,861.18 F
4	1	*COMPL, LH FRONT UPPER ARM	Bent	2,508.82 F	*2,508.82 F
5	1	*LOWER LH RIM	Bent	3,009.14 F	*3,009.14 F
6	1	*FRONT RIM	Cut	2,495.15 F	*2,495.15 F
7	1	*REAR RIM	Cut	2,542.74 F	*2,542.74 F
8	2	*TYRE PRESSURE MONITORING SYSTE	Necessary	1,021.20 F	*1,021.20 F
9	2	*VALVE	Necessary	128.10 F	*128.10 F
10	1	*STEERING BOX	Bent	10,689.46 F	*10,689.46 F
11	2	*WASHER	Necessary	5.02 F	*5.02 F
12	1	*LH FLANK	Repair	37,850.44 F	*- F
13	1	*FRONT LH FENDER	Dented	10,763.71 F	*10,763.71 F
14	1	*ADJUSTMENT SHIM (6PCS)	Necessary	86.54 F	*86.54 F
15	1	*ADJUSTMENT SHIM (2PCS)	Necessary	28.85 F	*28.85 F
16	1	*FORK ADJUSTER SHIM (10PCS)	Necessary	47.87 F	*47.87 F
17	1	*FORK ADJUSTER SHIM (6PCS)	Necessary	28.72 F	*28.72 F
18	1	*RIVET M6X16 (4PCS)	Necessary	12.93 F	*12.93 F
19	1	*RIVET (60PCS)	Necessary	102.00 F	*102.00 F
20	1	*RIVET (60PCS)	Necessary	114.00 F	*114.00 F
21	1	*COMPL LH FRONT SUBFRAME	Bent	1,670.02 F	*1,670.02 F
22	1	*COMPL. LH DOOR STRUCTURE	Dented	16,718.42 F	*16,718.42 F
23	1	*SCREW (6PCS)	Necessary	27.42 F	*27.42 F
24	1	*RH FRONT WHEELHOUSE	Necessary	1,050.39 F	*1,050.39 F
25	1	*LH FRONT WHEELHOUSE	Torn	1,050.39 F	*1,050.39 F
26	1	*FRONT DUCT FOR LH LOWER LATERA	Broken	67.27 F	*67.27 F
27	1	*LH REAR QUARTERLIGHT	Not Necessary	1,173.79 F	*- F
28	1	*COMPL FRONT BUMPER	Broken	21,536.67 F	*21,536.67 F
29	1	*COMPL LH LATERAL LOWER AERO F	Broken	4,575.36 F	*4,575.36 F
30	1	*LH LOWER LATERAL REINFORCEMENT	Bent	280.80 F	*280.80 F
31	1	*RIVET (30PCS)	Necessary	80.40 F	*80.40 F
32	1	*LH LATERAL MESH	Bent	170.76 F	*170.76 F
33	1	*COMPL REAR MESH	Broken	25,129.43 F	*25,129.43 F
34	2	*SCREW	Necessary	3.00 F	*3.00 F
35	1	*RIVET M6X16 (2PCS)	Necessary	6.46 F	*6.46 F
36	1	*LH EXTERNAL REAR VIEW MIRROR	Broken	1,889.68 F	*1,889.68 F
37	1	*LH EXTERNAL REAR MIRROR	Broken	391.81 F	*391.81 F
38	1	*HORN, LOW NOTE	Broken	143.00 F	*143.00 F
39	1	*LH HEADLAMP	Cut	7,106.22 F	*7,106.22 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*LATERAL TURN INDICATOR	Cut	174.48 F	*174.48 F
41	10		*FASTENER CLIP	Necessary	39.00 F	*39.00 F
42	1		*LH DOOR WINDOW	Cut	1,211.79 F	*1,211.79 F
43	1		*COMPLETE EXTERNAL LH FENDER FASTENER BRACKET	Bent	1,523.53 F	*1,523.53 F
44	2		*PENTOSIN CHF 11S	Necessary	140.00 F	*140.00 F

F=Franchise part.

Total Parts (\$\$) 167,962.01 127,243.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT, WELD, REPAIR - FRONT TRELIS, REAR LEFT FENDER (TO BE REPLACED ON CAR BENCH FOR REPAIR). REMOVE AND REPLACE DAMAGED PARTS, FRONT BUMPER & ACCESSORIES, REAR BUMPER & DIFFUSER (REPAIR), LEFT DOOR, LEFT FRONT FENDER, LEFT SIDE SKIRT (REPAIR), QUARTER GLASS, LEFT SIDE MIRROR, LEFT HEADLIGHT, RADIATOR FAN AIR DUCTS, STEERING BOX, FRONT ARMS AND KNUCKLE, WHEEL HOUSING, 2XWHEEL/RIMS, ETC	New	69,120.00	44,160.00
2	RESPRAY PAINT-FRONT BUMPER, REAR BUMPER, LEFT DOOR, LEFT SIDE SKIRT, FRONT LEFT FENDER, REAR LEFT FENDER, LEFT SIDE MIRROR, DIFFUSER, FRONT AND REAR INTERNAL STRUCTURES	New	16,500.00	13,200.00
3	DIAGNOSTIC CHECK AND TEST DRIVE, TOP UP AIRCON GAS, REPLACE SOLAR FILM ON QUARTER GLASS, WHEEL ALIGNMENT ETC	New	1,680.00	1,680.00
			Gross Labour Cost (\$)	87,300.00
				59,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >