

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010653/EPA3Q2-1**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100440295
Claimant Vehicle No :	SHA9439J	Insured Vehicle No :	SKX1231L
Date of Loss:	03/10/2020	Nature of Claim:	TP
		Claim No:	2420469134SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9439J	Engine No:	2ZRS050071
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU603559307
Reg. Date:	12/07/2017 (Man. Year: 2017)	Odometer:	474176 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firestone 5 mm	Rear Left Side:	Firestone 5 mm
Front Right Side:	Firestone 5 mm	Rear Right Side:	Firestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,912.00	2,480.00	432.00	14.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,590.00	570.00	26.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,072.00	4,070.00	1,002.00	19.76
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	5,072.00	3,250.00	1,822.00	35.92
+ GST 7.00/7.00% (S\$)	355.04	227.50	127.54	35.92
Nett Amount (S\$)	5,427.04	3,477.50	1,949.54	35.92
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.40/day) (S\$)		627.00		
(S\$)		4,354.50		
Liable Amount (40.00%) (S\$)		1,741.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,743.80		
Global Sum Settlement (S\$)		1,700.00		

INSPECTION

Date of Assignment:	03/10/2020	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/10/2020	Inspected At: 59 Loyang Drive
Estimated Period of Repair:	4.0 days	Singapore 508969

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,264.00 FL	*1,264.00 FL
2	1		*REAR DOOR RH	Dented	1,258.30 FL	*1,258.30 FL
3	1		*ROCKER PANEL GARNISH RH	Repair	576.00 FL	*- FL
4	1		*FRT DOOR COMFORTDELGRO RH	Necessary	75.00 FS	*75.00 FS
5	1		*REAR DOOR APPS STICKER RH	Necessary	80.00 FS	*80.00 FS
6	1		*REAR WHEEL CAP RH	Cut	177.70 FL	*177.70 FL
7	1		*FRT DOOR ADV STICKER RH	Necessary	100.00 FS	*100.00 FS
8	1		*REAR DOOR ADV STICKER RH	Necessary	100.00 FS	*100.00 FS
9	1		*REAR FENDER ADV.STICKER RH	Necessary	100.00 FS	*100.00 FS
					Sub Total (\$)	3,731.00
					- List Item Discount on L Items 25.00/25.00% (\$)	819.00
					Total Parts (\$)	2,912.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING -REAR FENDER RH ETC	New	700.00	640.00
2	SPRAYPAINT CHARGE	New	1,000.00	800.00
3	TUFF COAT ON AFFECTED PARTS	New	100.00	30.00
4	TRANSFER OF DOORS	New	240.00	60.00
5	WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$)			2,160.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >