

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 6413A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP - RH	NOT NECESSARY	1,020.00	-
1	FRONT FENDER - RH	DENTED	754.10	754.10
1	FRONT FENDER COWLING - RH	NOT NECESSARY	155.20	-
10	FRONT FENDER COWLING CLIPS @\$7.50	NOT NECESSARY	75.00	-
1	FRONT FENDER MUD FLAP - RH	NOT NECESSARY	155.00	-
1	FRONT TYRE - RH	NOT NECESSARY	300.00	-
1	SPORT RIM - RH	NOT NECESSARY	400.00	-
1	FRONT BUMPER	NOT NECESSARY	685.00	-
2	FRONT BUMPER SIDE BRACKET @\$112.00	NOT NECESSARY	224.00	-
8	FRONT BUMPER CLIPS @\$6.50	NOT NECESSARY	52.00	-
1	FRONT DOOR - RH	DENTED	1,086.80	1,086.80
1	FRONT DOOR SIDE MIRROR - RH	CUT	412.00	412.00
1	FRONT DOOR TOP HINGES - RH	NOT NECESSARY	112.00	-
1	FRONT DOOR LOWER HINGES - RH	NOT NECESSARY	112.00	-
1	FRONT DOOR OUTER HANDLE - RH	NOT NECESSARY	155.00	-
1	FRONT DOOR RUBBER - RH	NOT NECESSARY	215.00	-
1	FRONT DOOR INNER LOCK - RH	NOT NECESSARY	325.00	-
1	FRONT DOOR INNER GEAR	DAMAGED	385.00	385.00
1	FRONT DOOR INNER MOTOR	NOT NECESSARY	422.00	-
1	FRONT DOOR TOP MOULDING	NOT NECESSARY	125.00	-
1	FRONT DOOR INNER TRIM BOARD	CRACKED	658.00	658.00
	LESS 20% DISCOUNT		-	-659.18
			7,828.10	2,636.72
	<u>LABOUR</u>			
	TO REMOVE & RE-FIX CUSHION.	NOT NECESSARY	120.00	-
	TO REMOVE & RE-FIX FRONT RH DOOR FITTINGS.		200.00	80.00
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TO CHECK WHEEL ALIGNMENT COMPUTER.	NOT NECESSARY	120.00	-
	TUFF KOTE.		120.00	30.00
	PANEL BEATING.		1,000.00	500.00

Report Ref No. CS/AGI22004974/Any3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,000.00	500.00
			2,620.00	1,140.00
GRAND TOTAL			10,448.10	3,776.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/AGI22004974/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.