

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004977/UVY3M4**Date:** 10/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00005342100

Claimant Vehicle No : SKL5739B **Insured Vehicle No :** SNA1421R

Date of Loss: 25/05/2022 Nature of Claim: TP Claim No: SNM22D203660/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL5739B**

Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CXS008510

Reg. Date: 28/11/2013 (Man. Year: 2013) Chassis No: WAUZZZ8V4EA009235

Colour: White Odometer: 68327 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,935.55	9,143.23	792.32	7.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,340.00	1,660.00	55.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,935.55	10,483.23	2,452.32	18.96
Approved Total (Overridden) (S\$)		8,350.00		
(S\$)	12,935.55	8,350.00	4,585.55	35.45
+ GST 7.00/7.00% (S\$)	905.49	584.50	320.99	35.45
Nett Amount (S\$)	13,841.04	8,934.50	4,906.54	35.45

INSPECTION

Date of Assignment: 26/05/2022

Date Inspected: 26/05/2022 Inspected At: TAN LIM MOTOR PTE LTD (DEFU)
1 DEFU LANE 6
SINGAPORE 539365

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2022)
Parts:	143	AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL5739B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,403.55 FL	*1,403.55 FL
2	1		*FRONT BUMPER FOG LAMP TRIM	Grazed	79.55 FL	*79.55 FL
3	1		*FRONT BUMPER FOAM	Torn	59.80 FL	*59.80 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	522.65 FL	*522.65 FL
5	1		*O/S FRONT BUMPER SIDE RETAINER	Cracked	45.10 FL	*45.10 FL
6	1		*O/S HEADLAMP	Cracked	2,059.85 FL	*2,059.85 FL
7	1		*O/S HEADLAMP CONTROL UNIT	Damaged	974.85 FL	*974.85 FL
8	1		*O/S HEADLAMP WIPER NOZZEL	Cracked	158.65 FL	*158.65 FL
9	1		*O/S HEADLAMP WIPER NOZZEL COVER	Torn	41.10 FL	*41.10 FL
10	1		*BONNET	Bent	2,122.20 FL	*2,122.20 FL
11	12		*BONNET INSULATOR PADDING CLIP @\$2.50	Not Necessary	30.00 FL	*- FL
12	1		*BONNET UNDER SEAL	Not Necessary	29.95 FL	*- FL
13	1		*BONNET LOCK	Not Necessary	147.20 FL	*- FL
14	1		*O/S FRONT FENDER	Cracked	632.75 FL	*632.75 FL
15	1		*O/S FRONT FENDER INNER TRIM COWLING	Torn	124.65 FL	*124.65 FL
16	1		*SET O/S FRONT FENDER INNER TRIM COWLING CLIP	Necessary	52.85 FL	*52.85 FL
17	1		*O/S FRONT FENDER EXTENSION	Bent	71.35 FL	*71.35 FL
18	1		*SUPPORT PANEL	Not Necessary	575.10 FL	*- FL
19	1		*SUPPORT PANEL TOP GARNISH	Not Necessary	62.45 FL	*- FL
20	1		*O/S AIR GUIDE	Not Necessary	35.65 FL	*- FL
21	1		*O/S FRONT RIM	Grazed	450.00 FL	*450.00 FL
22	1		*FRONT GRILLE	Cracked	1,077.95 FL	*1,077.95 FL
23	1		*FRONT BUMPER UNDER COVER	Torn	282.30 FL	*282.30 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,039.50	10,159.15
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,103.95	1,015.92
Total Parts (\$\$)	9,935.55	9,143.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	1,200.00	520.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	1,200.00	700.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	80.00	20.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	80.00	60.00
5	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING.	New	50.00	0.00
6	TO DISMANTLE AIR-CON ASSY, REMOVE AND RENEWAL OF PARTS, VACUUM AND CHARGE-IN GAS.	New	140.00	0.00
7	TO TOUP RADIATOR COOLANT.	New	50.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	200.00	40.00
Gross Labour Cost (\$\$)			3,000.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >