

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004978/BNY3Q2**Date:** 15/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00034722200

**Claimant Vehicle No :** SNB5853X**Insured Vehicle No :** SDM833Y

Date of Loss: 24/05/2022

Nature of Claim: TP

Claim No: SNM22D203655/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNB5853X**

Make &amp; Model: HONDA SHUTTLE, 1.5 (A)

Engine No: L15B6023862

Reg. Date: 30/08/2021 (Man. Year: 2019)

Chassis No: GK82103320

Colour: Purple

Odometer: 40938 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Yokohama 5 mm

Rear Left Side:

Davanti 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Davanti 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,013.84	2,852.96	8,160.88	74.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	1,140.00	3,490.00	75.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>15,643.84</b>	<b>3,992.96</b>	<b>11,650.88</b>	<b>74.48</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,200.00</b>		
<b>Nett Amount (\$\$)</b>	<b>15,643.84</b>	<b>3,200.00</b>	<b>12,443.84</b>	<b>79.54</b>

**INSPECTION**

Date of Assignment: 12/08/2022

Date Inspected: 26/05/2022 Inspected At:

Team Auto Pro Pte Ltd - Sin Ming (HQ)  
160 Sin Ming Drive #01-14 Sin Ming Autocity  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** Lim Teow Guan**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 15 Aug 2022)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNB5853X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,458.90 FL	*1,254.80 FL
2	1		*TAILGATE LOGO	Necessary	78.00 FL	*38.00 FL
3	1		*TAILGATE OUTER GARNISH	Not Damaged	471.00 FL	*- FL
4	1		*TAILGATE OUTER CHROME MOULDING	Not Damaged	165.00 FL	*- FL
5	1		*TAILGATE EMBLEM SHUTTLE	Necessary	110.00 FL	*52.00 FL
6	1		*TAILGATE INNER LOCK	Jammed	258.70 FL	*157.10 FL
7	1		*TAILGATE WEATHERSTRIP	Torn	215.00 FL	*189.00 FL
8	2		*TAILGATE LAMP	Not Damaged	1,565.20 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Damaged	476.80 FL	*- FL
10	1		*TAILGATE INNER HANDLE GARNISH	Not Damaged	168.90 FL	*- FL
11	2		*TAILGATE WINDSCREEN MOULDING SIDE	Necessary	173.00 FL	*144.00 FL
12	1		*TAILGATE WINDSCREEN MOULDING TOP	No such part	108.20 FL	*- FL
13	1		*TAILGATE WINDSCREEN MOULDING BOTTOM	Necessary	108.20 FL	*108.20 FL
14	1		*TAILGATE ANTENNA SENSOR	Not Damaged	228.00 FL	*- FL
15	1		*TAILGATE SMART BUZZER	Not Damaged	195.00 FL	*- FL
16	1		*REAR BUMPER	Broken	1,150.60 FL	*985.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	211.20 FL	*77.00 FL
18	2		*REAR BUMPER REFLECTOR	Not Damaged	297.20 FL	*- FL
19	2		*REAR BUMPER SIDE SPONGE	Not Damaged	228.40 FL	*- FL
20	1		*REAR BUMPER OUTER CHROME MOULDING	Cracked	148.60 FL	*148.60 FL
21	1		*REAR END PANEL CENTRE	Not Damaged	985.30 FL	*- FL
22	2		*REAR END PANEL SIDE	Not Damaged	1,131.20 FL	*- FL
23	1		*REAR END PANEL TOP GARNISH	Not Damaged	177.00 FL	*- FL
24	2		*TAILLAMP	Not Damaged	1,970.40 FL	*- FL
25	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
26	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
27	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
29	1		*TAILGATE WINDSCREEN INNER SEAL	No such part	60.00 FS	*- FS
30	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
32	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*REAR BUMPER OUTER CHROME MOULDING CLIPS	Not Necessary	50.00 FS	*- FS
34	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
35	1		*REAR END PANEL SEALANT	Not Damaged	100.00 FS	*- FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Not Damaged	50.00 FS	*- FS
37	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,429.80</b>	<b>3,483.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,415.96	630.74
<b>Total Parts (\$\$)</b>	<b>11,013.84</b>	<b>2,852.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	R&R REVERSE CAMERA	New	100.00	0.00
4	CHECK WIRING	New	100.00	0.00
5	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
8	PANEL BEATING	New	1,600.00	600.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,600.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,630.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >