

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22004981/ANY3E2

**Date:** 15/07/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00211852100  
**Claimant Vehicle No :** SMN3562Y **Insured Vehicle No :** SMQ2034X  
Date of Loss: 18/05/2022 Nature of Claim: TP Claim No: SNM22D203492/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN3562Y**  
Make & Model: TOYOTA HARRIER, 2.0 (A) Engine No: 8ARZ165291  
Reg. Date: 01/08/2019 (Man. Year: 2019) Chassis No: JTEKB3GH10J004872  
Colour: White Odometer: 71641 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/50R19 Rear Tyre Size: 255/50R19  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,232.40	4,945.82	9,286.58	65.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,780.00	1,800.00	2,980.00	62.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,012.40</b>	<b>6,745.82</b>	<b>12,266.58</b>	<b>64.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>19,012.40</b>	<b>5,400.00</b>	<b>13,612.40</b>	<b>71.60</b>

### INSPECTION

Date of Assignment: 26/05/2022  
Date Inspected: 26/05/2022 Inspected At: KS AUTOMOBILE (HQ)  
60 JALAN LAM HUAT, CARROS CENTRE, #05-68  
Singapore 737869  
Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2022)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMN3562Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,110.00 FL	*1,866.00 FL
2	1		*TAILGATE WEATHERSTRIP	Cut	248.00 FL	*248.00 FL
3	1		*TAILGATE LOCK	Damaged	480.00 FL	*480.00 FL
4	1		*TAILGATE INNER TRIM BOARD	Not Necessary	515.00 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	85.00 FL	*85.00 FL
6	1		*TAILGATE EMBLEM HARRIER	Necessary	75.00 FL	*75.00 FL
7	1		*TAILGATE EMBLEM TURBO	Necessary	68.00 FL	*68.00 FL
8	2		*TAILGATE DAMPER	Not Necessary	430.00 FL	*- FL
9	1		*TAILGATE DETECTOR SENSOR	Not Necessary	310.00 FL	*- FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	218.00 FL	*218.00 FL
11	2		*TAILLAMP LOWER BRACKET	Not Necessary	318.00 FL	*- FL
12	1		*REAR BUMPER (UPPER)	Deformed	1,459.00 FL	*955.00 FL
13	1		*REAR BUMPER LOWER GARNISH	Deformed	712.00 FL	*397.00 FL
14	2		*REAR BUMPER BRACKET	Not Necessary	76.90 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINER	Not Necessary	204.00 FL	*- FL
16	2		*REAR BUMPER REFLECTOR	Not Necessary	248.60 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Not Necessary	317.00 FL	*- FL
18	1		*REAR BUMPER SPONGE	Cracked	345.70 FL	*345.70 FL
19	2		*REAR FENDER COWLING	Not Necessary	430.40 FL	*- FL
20	2		*REAR FENDER INNER TRIM	Not Necessary	1,596.00 FL	*- FL
21	1		*REAR END PANEL	Repair	655.40 FL	*- FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	395.40 FL	*395.40 FL
23	2		*REAR SIDE COMPARTMENT	Not Necessary	796.40 FL	*- FL
24	2		*REAR CENTRE COMPARTMENT TOP	Not Necessary	850.00 FL	*- FL
25	2		*REAR FLOOR TOP BOARD	Not Necessary	1,398.40 FL	*- FL
26	2		*REAR FLOOR SIDE BOARD	Not Necessary	310.00 FL	*- FL
27	1		*REAR FLOOR MAT	Not Necessary	688.00 FL	*- FL
28	1		*REAR EXHAUST SILENCER	Not Necessary	1,215.00 FL	*- FL
29	1		*REAR BUMPER INNER DAMPER	Bent	1,048.00 FL	*1,048.00 FL
30	1		*REAR REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
31	1		*SET REAR BUMPER UPPER CLIP	Necessary	50.00 FS	*30.00 FS
32	1		*REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
33	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*TAILGATE INNER SEAL	Necessary	80.00 FS	*30.00 FS
36	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
37	1		*END PANEL TOP GARNISH CHROME	Not Necessary	150.00 FS	*- FS
38	1		*END PANEL SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>18,633.20</b>	<b>6,491.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	4,400.80	1,545.28
<b>Total Parts (\$\$)</b>	<b>14,232.40</b>	<b>4,945.82</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	180.00	50.00
3	TO REMOVE AND REFIT TAILGATE WINDSCREEN GLASS	New	150.00	120.00
4	TO REMOVE AND REFIT TAILGATE MECHANISM	New	150.00	80.00
5	TO REMOVE AND REFIT EXHAUST SYSTEM	New	120.00	0.00
6	APPLY REAR BUMPER COATING	New	250.00	200.00
7	REMOVE AND REFIT CUSHION, UPHOLSTERY	New	300.00	60.00
8	TO RESPRAY UNDERCOATING	New	150.00	60.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	0.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	600.00
11	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,780.00</b>	<b>1,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >