



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 4366H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MEMBER PANEL, LH	BROKEN	149.33	149.33
1	MEMBER PANEL, CENTER	CRUSHED	108.00	108.00
1	WIPER LINK	TO REPAIR SEE LABOUR	672.00	-
1	WIPER LINK BRACKET	BENT	694.00	694.00
1	AIR DUCT ASSY	NOT NECESSARY	718.50	-
1	FRONT UPPER PANEL	DENTED	1,577.00	1,577.00
1	SPACE FRAME	DENTED	2,155.00	2,155.00
	LESS 10% DISCOUNT		-607.38	-468.33
			5,466.45	4,215.00
	<u>LABOUR</u>			
	REMOVE AND REPLACE DAMAGED PARTS AS ABOVE. INCLUDING JACK, STRAIGHTEN AND REALIGN FRONT DASH PANEL TOP FRAME. (\$350 x 4 DAYS). INCLUSIVE OF THE REPAIR OF WIPER LINK.		1,400.00	525.00
	VACUUM AND REPLENISH AIRCON GAS.	NOT NECESSARY	120.00	-
	SPRAY PAINTING.		400.00	250.00
			1,920.00	775.00
	GRAND TOTAL		7,386.45	4,990.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CS/AWA22004983/Eqy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.