



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 977P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	585.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	105.00	-
1	REAR N/S BUMPER SIDE RETAINER	SERVICEABLE	135.00	-
2	REAR N/S BUMPER SENSOR @\$305.00	SCRATCHED (1PIECE ONLY)	610.00	305.00
1	REAR N/S BUMPER REFLECTOR	SERVICEABLE	195.00	-
1	REAR N/S EXHAUST SILENCER	TO REPAIR SEE LABOUR	955.00	-
	LESS 10% DISCOUNT		-258.50	-30.50
			2,326.50	274.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CUSTOMISE (SN)	CRACKED	1,500.00	1,500.00
10	REAR BUMPER CLIP @\$4.00 (SN)	NECESSARY	40.00	40.00
			1,540.00	1,540.00
	<u>LABOUR</u>			
	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR N/S EXHAUST SILENCER.		600.00	250.00
	TO PUTTY AND SPRAY PAINT.		600.00	280.00
	CHECK & RECONNECT WIRING.		30.00	15.00
	REMOVE/RENEW REAR BUMPER SENSOR INCLUDING RESET SAME.		248.00	60.00
	REMOVE/RENEW REAR EXHAUST SILENCER.		400.00	80.00
			1,878.00	685.00
	GRAND TOTAL		5,744.50	2,499.50

Report Ref No. CS/SMO22004984/Kqy3m4



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	-----------------

Report Ref No. CS/SMO22004984/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.