

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122004989/UVY3N2**Date:** 10/06/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLW2508B**Insured Vehicle No :** GBD8670T

Date of Loss: 23/05/2022

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLW2508B**

Make & Model: MAZDA 3, 1.6 (A)

Engine No: P520476668

Reg. Date: 21/11/2017 (Man. Year: 2017)

Chassis No: JM6BN22A8J0186365

Colour: Blue

Odometer: 65797 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size:

205/60R16

Front Left Side: Firenza 6 mm

Rear Left Side:

Toyo 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side:

Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,852.80	2,175.04	677.76	23.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	970.00	280.00	22.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,102.80	3,145.04	957.76	23.34
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	4,102.80	2,500.00	1,602.80	39.07
+ GST 7.00/7.00% (S\$)	287.20	175.00	112.20	39.07
Nett Amount (S\$)	4,390.00	2,675.00	1,715.00	39.07

INSPECTION

Date of Assignment: 26/05/2022

Date Inspected: 30/05/2022 Inspected At:

Car City Auto Centre Pte Ltd (HQ)
Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
Parts:	144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW2508B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cracked	1,070.00 F	*1,070.00 FL
2	1		*FRONT BUMPER	Torn	966.00 F	*966.00 FL
3	1		*FRONT BUMPER RETAINER RH	Bent	24.00 F	*24.00 FL
4	1		*RHF FENDER	Dented	349.00 F	*349.00 FL
5	1		*RHF FENDER INNER SHIELD	Torn	135.00 F	*135.00 FL
6	6		*RHF FENDER INNER SHIELD CLIP	Necessary	28.80 F	*28.80 FL
7	1		*WASHER TANK	Deformed	146.00 F	*146.00 FL
8	1		*WASHER TANK MOTOR	Not Necessary	134.00 F	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					2,852.80	2,718.80
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	543.76
Total Parts (S\$)					2,852.80	2,175.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR,REPLACE,BONNET,FRONT BUMPER,RHF FENDER AND AFFECTED AREA	New	500.00	450.00
2	TO PUTTY AND SPRAY PAINT ON BONNET,FRONT BUMPER,RHF FENDER AND AFFECTED AREA	New	700.00	500.00
3	TO CHECK WIRING	New	50.00	20.00
Gross Labour Cost (\$\$)			1,250.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >