

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004991/KNY3M4**Date:** 08/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00187272100	
Claimant Vehicle No :	GBF2364G	Insured Vehicle No :	SMX8443Y	
Date of Loss:	24/05/2022	Nature of Claim:	TP	Claim No: SNM22D203612/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2364G		Engine No:	YD25397717A
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)		Chassis No:	JN1MC2E26Z0006639
Reg. Date:	08/08/2016 (Man. Year: 2016)		Odometer:	119937 km
Colour:	Metallic Dark Brown			
Engine Capacity:	2488 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,048.16	3,280.49	3,767.67	53.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,800.00	560.00	23.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,408.16	5,080.49	4,327.67	46.00
+ GST 7.00/7.00% (\$\$)	658.57	355.63	302.94	46.00
Nett Amount (\$\$)	10,066.73	5,436.12	4,630.61	46.00

INSPECTION

Date of Assignment:	26/05/2022	
Date Inspected:	27/05/2022	Inspected At: AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Aug 2022)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF2364G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,100.00 FL	*1,986.70 FL
2	1		*TAILGATE EMBLEM	Necessary	78.00 FL	*78.00 FL
3	1		*TAILGATE NV350 LOGO	Necessary	110.00 FL	*110.00 FL
4	1		*TAILGATE URVAN LOGO	Necessary	64.90 FL	*64.90 FL
5	1		*TAILGATE LOCK	Repair	330.00 FL	*- FL
6	16		*TAILGATE INNER TRIM CLIPS	Not Necessary	88.00 FL	*- FL
7	1		*TAILGATE RUBBER	Serviceable	155.00 FL	*- FL
8	1		*TAILAMP RH	Cracked	255.00 FL	*255.00 FL
9	1		*TAILAMP GROMMET TOP	Serviceable	5.50 FL	*- FL
10	1		*TAILAMP GROMMET BTM	Serviceable	5.50 FL	*- FL
11	1		*REAR BUMPER	Bent	667.00 FL	*667.00 FL
12	4		*REAR BUMPER SIDE RETAINER RH	Distorted	56.00 FL	*56.00 FL
13	7		*REAR BUMPER CLIPS	Necessary	38.50 FL	*38.50 FL
14	3		*REAR BUMPER GROMMET	Serviceable	16.50 FL	*- FL
15	1		*REAR STEP PANEL	Repair	210.00 FL	*- FL
16	1		*REAR END PANEL OUTER	Repair	217.00 FL	*- FL
17	1		*REAR END PANEL INNER	Repair	576.00 FL	*- FL
18	1		*REAR FENDER OUTER RH	Repair	2,300.00 FL	*- FL
19	17		*REAR FENDER INNER TRIM CLIPS	Not Necessary	93.50 FL	*- FL
20	1		*REAR AIR VENT	Serviceable	76.00 FL	*- FL
21	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
22	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
23	1		*TAILGATE STICKER 8 PAX	Necessary	10.00 FS	*10.00 FS
24	1		*TAILGATE STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
25	1		*TAILGATE STICKER COMPANY NAME - CHECK PRICE	Necessary	70.00 FS	*70.00 FS
26	1		*TAILGATE STICKER MASCOT - CHECK PRICE (NPA)	Not Necessary	0.00 FS	*- FS
27	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
28	1		*REAR FENDER STICKER RH - CHECK PRICE (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,792.40	3,606.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	744.24	325.61
Total Parts (\$\$)	7,048.16	3,280.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS	New	80.00	0.00
4	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	60.00	50.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	60.00
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL, REAR OUTER FENDER RH, TO KNOCK & REPAIR REAR FLOOR PANEL, REAR INNER FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	1,000.00	750.00
7	TO SPRAY TAILGATE, REAR END PANEL, REAR FENDER RH, REAR FLOOR PANEL	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,360.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >