



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 6974L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	CRACKED	1,109.00	1,082.40
1	FRONT BUMPER LH RETAINER (CONSISTENT)	DISTORTED	22.00	22.00
1	LH FOG LAMP GARNISH (CONSISTENT)	DENTED	79.00	79.00
1	LH FOG LAMP (CONSISTENT)	SERVICEABLE	340.00	-
1	FRONT LH FENDER (CONSISTENT)	BENT	323.00	323.00
1	FRONT LH FENDER INNER SHIELD (CONSISTENT)	CRACKED	217.00	211.00
1	LH HEAD LAMP (CONSISTENT)	CUT	1,482.00	1,482.00
1	FRONT SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	266.00	-
1	FRONT LH LOWER ARM (CONSISTENT)	SERVICEABLE	411.00	-
1	FRONT LH KNUCKLE ARM (CONSISTENT)	SERVICEABLE	386.00	-
1	LH SIDE GARNISH (CONSISTENT)	DISTORTED	80.00	80.00
	LESS 20% DISCOUNT		-	-655.88
			4,715.00	2,623.52
	<u>SPECIAL NETT ITEMS</u>			
1	SPORT RIM (SN) (CONSISTENT)	DENTED	250.00	250.00
			250.00	250.00
	<u>LABOUR</u>			
	REMOVE & FIX BACK FRONT BUMPER ,FENDER ,HEAD LAMP .		500.00	400.00
	REMOVE & FIX BACK UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	WHEEL ALIGNMENT.		120.00	60.00
	SPRAY PAINTING.		800.00	600.00
			1,770.00	1,060.00
	GRAND TOTAL		6,735.00	3,933.52
	RECOMMENDED COST OF REPAIRS			3,933.52

Report Ref No. CC4/ASM22004993/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.