

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22004995/UQY3E2

Date: 17/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961699		
Claimant Vehicle No :	SMY2195Y	Insured Vehicle No :	SLR2141B		
Date of Loss:	25/05/2022	Nature of Claim:	TP	Claim No:	275167

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY2195Y	Engine No:	FA20J937533
Make & Model:	SUBARU FORESTER, 2.0 XT (A)	Chassis No:	JF1SJGK85EG040015
Reg. Date:	30/03/2015 (Man. Year: 2014)	Odometer:	135644 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50ZR18	Rear Tyre Size:	245/50ZR18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,656.00	5,660.56	10,995.44	66.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,880.00	1,730.00	47.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,266.00	7,540.56	12,725.44	62.79
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	20,266.00	6,000.00	14,266.00	70.39
+ GST 7.00/7.00% (S\$)	1,418.62	420.00	998.62	70.39
Nett Amount (S\$)	21,684.62	6,420.00	15,264.62	70.39

INSPECTION

Date of Assignment:	26/05/2022		
Date Inspected:	30/05/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2022)
Parts:	M1-SUV	SUBARU FORESTER 2.0 XT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY2195Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Dented/Bent	1,125.00 F	*720.40 FL
2	1		*FRONT DOOR OUTER LOWER PROTECTOR O/S	Warped	488.00 F	*290.70 FL
3	1		*FRONT DOOR INNER LOCK O/S	Not Necessary	450.00 F	*- FL
4	1		*FRONT DOOR INNER RUBBER O/S	Necessary	202.00 F	*98.50 FL
5	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed/Torn	980.00 F	*554.90 FL
6	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	48.00 F	*48.00 FL
7	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Serviceable	490.00 F	*- FL
8	2		*FRONT DOOR HINGES O/S	Not Necessary	180.00 F	*- FL
9	1		*FRONT DOOR CHECKER O/S	Not Necessary	121.00 F	*- FL
10	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	80.00 F	*50.00 FL
11	1		*REAR DOOR O/S	Badly Dented	1,099.00 F	*720.80 FL
12	1		*REAR DOOR LOWER OUTER PROTECTOR O/S	Warped	450.00 F	*192.80 FL
13	1		*REAR DOOR INNER RUBBER O/S	Necessary	202.00 F	*98.50 FL
14	1		*REAR DOOR HINGES O/S	Lower Bent	180.00 F	*90.00 FL
15	1		*REAR DOOR CHECKER O/S	Twisted	122.00 F	*99.00 FL
16	1		*REAR DOOR INNER LOCK O/S	Not Necessary	450.00 F	*- FL
17	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed/Torn	950.00 F	*514.20 FL
18	1		*SET REAR DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 F	*50.00 FL
19	1		*REAR DOOR GLASS REGULATOR & MOTOR O/S	Bent	485.00 F	*291.00 FL
20	1		*SET REAR DOOR FRAME BLACK STICKER O/S	Necessary	80.00 F	*50.00 FL
21	1		*REAR FENDER O/S	Repair	1,250.00 F	*- FL
22	1		*REAR FENDER ARCH GARNISH O/S	Distorted	345.00 F	*118.20 FL
23	1		*REAR FENDER GLASS O/S	Not Necessary	680.00 F	*- FL
24	1		*REAR BUMPER	Dented	690.00 F	*600.50 FL
25	1		*REAR BUMPER SIDE RETAINER O/S	Bent	62.00 F	*38.00 FL
26	1		*REAR BUMPER REFLECTOR O/S	Scratched	68.00 F	*52.00 FL
27	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
28	1		*REAR BUMPER SPLASH SHIELD O/S	Torn	112.00 F	*108.20 FL
29	1		*REAR END PANEL	Repair	452.00 F	*- FL
30	1		*CENTRE PILLAR O/S	Repair	625.00 F	*- FL
31	1		*REAR WHEEL HUB BEARING O/S	Damaged	650.00 F	*390.00 FL
32	1		*REAR KNUCKLE ARM O/S	Not Necessary	800.00 F	*- FL
33	1		*FRONT DOOR VISOR O/S	Necessary	80.00 FS	*50.00 FS
34	1		*SET REAR DOOR SOUND PROOF INSULATOR O/S	Necessary	600.00 FS	*350.00 FS
35	1		*SET FRONT DOOR SOUND PROOF INSULATOR O/S	Necessary	600.00 FS	*350.00 FS
36	1		*REAR DOOR VISOR O/S	Necessary	80.00 FS	*50.00 FS
37	1		*REAR SPORT RIM O/S	Cut/Bent	800.00 FS	*680.00 FS
38	1		*REAR TYRE O/S	Serviceable	200.00 FS	*- FS
39	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,656.00	6,705.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,045.14
Total Parts (\$\$)	16,656.00	5,660.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOTH DOOR COMPONENTS	New	180.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR FENDER GLASS O/S	New	120.00	0.00
6	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	180.00	0.00
7	TO SPRAY RUST PROOFING	New	150.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	950.00
Gross Labour Cost (S\$)			3,610.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >