

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004998/UVY3N2**Date:** 29/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00102172100

Claimant Vehicle No : SFL8138A **Insured Vehicle No :** YN8843L

Date of Loss: 25/05/2022 Nature of Claim: TP Claim No: SNM22D203666/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFL8138A**

Make & Model: TOYOTA WISH, 1.8 X LIMITED (A) Engine No: 1ZZ2926012

Reg. Date: 22/11/2007 (Man. Year: 2007) Chassis No: ZNE100370021

Colour: Silver Odometer: 197105 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,050.22	2,976.72	1,073.50	26.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,570.00	490.00	23.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,110.22	4,546.72	1,563.50	25.59
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	6,110.22	3,600.00	2,510.22	41.08
+ GST 7.00/7.00% (\$\$)	427.72	252.00	175.72	41.08
Nett Amount (\$\$)	6,537.94	3,852.00	2,685.94	41.08

INSPECTION

Date of Assignment: 26/05/2022

Date Inspected: 20/06/2022 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 X LIMITED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFL8138A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR WINDSCREEN MOULDING	Necessary	180.00 FL	*180.00 FL
2	1		*REAR GATE	Badly Dented	1,275.00 FL	*1,275.00 FL
3	1		*REAR GATE LOGO	Necessary	55.00 FL	*55.00 FL
4	1		*REAR GATE CHROME MOULDING	Cracked	359.00 FL	*359.00 FL
5	1		*REAR GATE LOCK	Dented/Shorted	443.00 FL	*443.00 FL
6	1		*REAR BUMPER	Torn	560.30 FL	*560.30 FL
7	2		*REAR BUMPER RETAINER	Bent	90.00 FL	*90.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
9	1		*REAR BUMPER BRACKET	Dented	55.00 FL	*55.00 FL
10	1		*REAR BUMPER REFLECTOR RH	Not Necessary	48.00 FL	*- FL
11	2		*TAIL LAMP	Not Necessary	930.00 FL	*- FL
12	1		*REAR END PANEL	Dented	515.00 FL	*515.00 FL
13	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
14	1		*REAR GATE SEALANT	Not Necessary	60.00 FS	*- FS
15	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*50.00 FS
16	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
17	1		*REVERSE CAMERA	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,190.30	3,872.30
- List Item Discount on L Items 25.00/25.00% (\$)	1,140.08	895.58
Total Parts (\$)	4,050.22	2,976.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	20.00	20.00
2	TRANSFER REAR GATE COMPONENT	New	100.00	60.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY	New	100.00	80.00
4	CAVITY PROTECTOR ON AFFECTED AREAS	New	100.00	40.00
5	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
6	REMOVE & REFIX SENSOR & REVERSE CAMERA	New	120.00	50.00
7	LABOUR CHARGE	New	750.00	600.00
8	SPRAY PAINTING	New	750.00	600.00
Gross Labour Cost (\$)			2,060.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >