

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004999/KTY3N2**Date:** 17/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00032602201	
Claimant Vehicle No :	SJH5362L	Insured Vehicle No :	SJN4374C	
Date of Loss:	24/05/2022	Nature of Claim:	TP	Claim No: SNM22D203633/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH5362L		Engine No:	3ZZ4778923
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)		Chassis No:	MR053ZEE106112569
Reg. Date:	13/08/2008 (Man. Year: 2008)		Odometer:	243628 km
Colour:	White			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,335.67	1,969.92	365.75	15.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,050.00	500.00	32.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,885.67	3,019.92	865.75	22.28
Approved Total (Overridden) (\$\$)		2,400.00		
(\$\$)	3,885.67	2,400.00	1,485.67	38.23
+ GST 7.00/7.00% (\$\$)	272.00	168.00	104.00	38.24
Nett Amount (\$\$)	4,157.67	2,568.00	1,589.67	38.23

INSPECTION

Date of Assignment:	26/05/2022	
Date Inspected:	27/05/2022 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH5362L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent/Cracked	497.00 FL	*497.00 FL
2	14		*REAR BUMPER CLIPS	Necessary	53.20 FL	*53.20 FL
3	1		*REAR BUMPER BRACKET RH	Bent	91.00 FL	*91.00 FL
4	1		*REAR BUMPER SPONGE	Serviceable	129.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Serviceable	37.00 FL	*- FL
6	1		*REAR BUMPER TOP RETAINER RH	Cracked	56.20 FL	*56.20 FL
7	1		*REAR BUMPER CORNER RETAINER RH	Distorted	73.50 FL	*73.50 FL
8	1		*REAR BUMPER SIDE HOLDER RH	Distorted	55.00 FL	*55.00 FL
9	1		*BOOT	Buckled	792.00 FL	*733.50 FL
10	1		*BOOT EMBLEM	Necessary	57.30 FL	*57.30 FL
11	1		*BOOT BADGE 1.6	Necessary	35.60 FL	*35.60 FL
12	1		*BOOT BADGE COROLLA	Necessary	46.50 FL	*46.50 FL
13	1		*BOOT BADGE ALTIS	Necessary	48.60 FL	*48.60 FL
14	1		*BOOT LAMP RH	Cut	185.00 FL	*185.00 FL
15	1		*BOOT LAMP GASKET	Necessary	55.00 FL	*55.00 FL
16	8		*BOOT TRIM BOARD CLIPS	Not Necessary	28.00 FL	*- FL
17	1		*TAILLAMP RH	Cut	386.00 FL	*317.50 FL
18	1		*TAILLAMP GASKET	Necessary	55.00 FL	*55.00 FL
19	1		*REAR BUMPER REVERSE SENSOR	Scratched	280.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,005.90	2,559.90
- List Item Discount on L Items 25.00/25.00% (\$)	670.23	589.98
Total Parts (\$)	2,335.67	1,969.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT REAR ELECTRICAL CHECK,REPLACE REVERSE SENSOR,MODULE REWIRING ETC	New	120.00	70.00
2	TO DISMANTLE/TRANSFER BOOT FITTINGS/ANCILLARY/ACCESSORIES	New	80.00	50.00
3	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	50.00	30.00
4	LABOUR CHARGE-PANEL BEATING,REPAIRING OF BOOT HINGES,END PANEL AND PART REPLACEMENT	New	600.00	400.00
5	TO RESPRAY AFFECTED AREAS	New	700.00	500.00
Gross Labour Cost (\$)			1,550.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >