

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22001980/RTY3E2-1

Date: 07/06/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0005530_02

Claimant Vehicle No : SLD1721H **Insured Vehicle No :** GBE2853S

Date of Loss: 28/02/2022 Nature of Claim: TP Claim No: MCV2022D0001028

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD1721H**
Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: LEB5080338
Reg. Date: 06/06/2016 (Man. Year: 2016) Chassis No: RU31130316
Colour: Black Odometer: 250766 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Crucero 6 mm Rear Left Side: Crucero 6 mm
Front Right Side: Crucero 6 mm Rear Right Side: Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,653.90	3,424.84	4,229.06	55.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,360.00	1,590.00	53.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,603.90	4,784.84	5,819.06	54.88
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	10,603.90	3,800.00	6,803.90	64.16

INSPECTION

Date of Assignment: 26/05/2022

Date Inspected: 07/03/2022 Inspected At:

Estimated Period of Repair: 5.0 days

A T Performance (SIN MING)
160 SIN MING DRIVE, #07-18/19 SIN MING
AUTOCITY
Singapore 575722

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1721H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Damaged	762.70 F	*762.70 FL
2	1		*REAR BUMPER SIDE	Not Necessary	237.40 F	*- FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	98.30 F	*- FL
4	1		*SET REAR BUMPER CLIP	Necessary	32.20 F	*32.20 FL
5	1		*REAR BUMPER SIDE REFLECTOR	Serviceable	141.10 F	*- FL
6	1		*REAR BUMPER LOWER COVER	Not Necessary	254.50 F	*- FL
7	1		*TAIL LAMP LH	Split / Damaged	580.00 F	*580.00 FL
8	1		*TAIL LAMP RH	Serviceable	580.00 F	*- FL
9	1		*TAIL GATE	Dented	1,209.10 F	*1,209.10 FL
10	1		*TAIL GATE BADGE - VEZEL	Necessary	68.60 F	*68.60 FL
11	1		*TAIL GATE LAMP LH	Damaged	387.60 F	*387.60 FL
12	1		*TAIL GATE LAMP RH	Serviceable	387.60 F	*- FL
13	1		*TAIL GATE LOCK	Not Necessary	213.40 F	*- FL
14	1		*TAIL GATE WEATHERSTRIP	Cut / Damaged	212.30 F	*212.30 FL
15	1		*TAIL GATE INNER TRIM BOARD	Folded	278.00 F	*278.00 FL
16	1		*SET TAIL GATE INNER TRIM BOARD CLIP	Necessary	36.40 F	*36.40 FL
17	1		*TAIL GATE INNER TRIM BOARD HANDLE	Serviceable	38.40 F	*- FL
18	1		*TAIL GATE GLASS MOULDING	Necessary	142.30 F	*142.30 FL
19	1		*REAR END PANEL	Repair	575.00 F	*- FL
20	1		*REAR END PANEL TOP GARNISH	Folded	142.50 F	*142.50 FL
21	1		*REAR END PANEL BUZZER	Cracked	85.60 F	*85.60 FL
22	1		*REAR END PANEL ANTENNA	Serviceable	78.20 F	*- FL
23	1		*REAR FENDER ARCH GARNISH	Not Necessary	182.70 F	*- FL
24	1		*SET REAR BUMPER PARKING AID SENSOR	Malfunction	300.00 FS	*200.00 FS
25	1		*REAR NUMBER PLATE	Damaged	50.00 FS	*35.00 FS
26	1		*REAR PANEL SEALANT	Necessary	100.00 FS	*- FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
28	1		*REVERSE CAMERA UNIT	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,653.90	4,212.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	787.46
Total Parts (\$\$)	7,653.90	3,424.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS. TO REMOVE AND TRANSFER TAIL GATE FITTINGS AND ATTACHMENTS	New	1,260.00	500.00
2	TO SUPPLY PAINT MATERIALS AND EXPANDABLE ITEMS. TO RESPRAY REAR AFFECTED PANELS	New	1,150.00	600.00
3	TO REMOVE / REFIT INTERIOR FITTINGS TO FACILITATE REPAIR	New	150.00	60.00
4	TO REMOVE AND TRANSFER REAR WINDSCREEN. TO CONDUCT WATER LEAK TEST	New	160.00	120.00
5	INSTALL REAR BUMPER SENSOR AND CHECK FOR PROPER FUNCTIONS	New	80.00	40.00
6	TO CARRY OUT ANTI RUST TREATMENT ON THE AFFECTED PANELS	New	150.00	40.00
Gross Labour Cost (\$\$)			2,950.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >