

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005006/AQY3Q2**Date:** 03/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00121492104
Claimant Vehicle No :	SMK6377L	Insured Vehicle No :	XE3566D
Date of Loss:	25/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203667/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6377L	Engine No:	1ZR0D31017
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH604596198
Reg. Date:	18/04/2019 (Man. Year: 2019)	Odometer:	44761 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,265.00	4,032.75	4,232.25	51.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	2,080.00	2,670.00	56.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,015.00	6,112.75	6,902.25	53.03
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	13,015.00	4,900.00	8,115.00	62.35
+ GST 7.00/7.00% (S\$)	911.05	343.00	568.05	62.35
Nett Amount (S\$)	13,926.05	5,243.00	8,683.05	62.35

INSPECTION

Date of Assignment:	27/05/2022	
Date Inspected:	27/05/2022	Inspected At: BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700 Repairer: Jack Cars Enterprise Pte Ltd (HQ)
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK6377L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,200.00 FL	*556.00 FL
2	1		*REAR BUMPER BRACKET -LEFT & RIGHT	Necessary	150.00 FL	*150.00 FL
3	1		*REAR BOOT	Dented	2,100.00 FL	*781.00 FL
4	1		*REAR BOOT HINGE -LEFT & RIGHT	Bent	180.00 FL	*180.00 FL
5	1		*REAR BOOT INNER COVER	Not Necessary	230.00 FL	*- FL
6	1		*REAR BOOT WEATHERSTRIP	Cut	320.00 FL	*271.00 FL
7	1		*REAR BOOT CHROME GARNISH	Cracked	190.00 FL	*190.00 FL
8	1		*REAR END PANEL	Dented	780.00 FL	*695.00 FL
9	1		*REAR END PANEL TOP COVER	Deformed	180.00 FL	*180.00 FL
10	1		*SPARE TYRE COMPARTMENT	Repair	1,000.00 FL	*- FL
11	1		*SPARE TYRE COMPARTMENT COVER	Not Necessary	230.00 FL	*- FL
12	1		*RIGHT LAMP -INNER LEFT	Cut	930.00 FL	*391.00 FL
13	1		*RIGHT TAIL LAMP -OUTER LEFT	Cut	640.00 FL	*358.00 FL
14	1		*RIGHT LAMP -INNER RIGHT	Cracked	930.00 FL	*391.00 FL
15	1		*RIGHT LAMP -OUTER RIGHT	Cracked	640.00 FL	*358.00 FL
16	1		*BOOT LOCK -UPPER	Damaged	320.00 FL	*320.00 FL
17	1		*BOOT LOCK -LOWER	Not Necessary	180.00 FL	*- FL
18	1		*CLIPS ,RIVETS & SCREWS	Necessary	100.00 FS	*30.00 FS
19	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
20	1		*TOYOTA EMBLEM	Necessary	100.00 FS	*65.00 FS
21	1		*COROLLA ALTIS EMBLEM	Necessary	95.00 FS	*62.00 FS
22	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,815.00	5,238.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,550.00	1,205.25
Total Parts (S\$)	8,265.00	4,032.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00	1,000.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS KNOCK ,JACK ,WELD ,RESHAPE AND ALIGN ALL AFFECTED PORTIONS	New	2,000.00	800.00
3	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	New	350.00	30.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	220.00	80.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	280.00	60.00
6	TO REMOVE & REINSTALL SENSORS	New	200.00	50.00
7	ANTI RUST TREATMENT	New	200.00	60.00
Gross Labour Cost (\$)			4,750.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >