



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 8944E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	YAMAHA FAIRING (COLORED)	SERVICEABLE	450.00	-
1	YAMAHA FAIRING (MATTE BLACK)	DEFORMED	140.00	140.00
1	YAMAHA SWINGARM	SERVICEABLE	480.00	-
1	YAMAHA SWINGARM SHAFT	SERVICEABLE	80.00	-
1	YAMAHA SWINGARM BUSHING KIT	SERVICEABLE	120.00	-
1	YAMAHA SWINGARM BEARING KIT	SERVICEABLE	80.00	-
1	YAMAHA REAR SUSPENSION	SERVICEABLE	380.00	-
1	YAMAHA REAR RIM	SERVICEABLE	280.00	-
2	YAMAHA REAR WHEEL BEARING	SERVICEABLE	70.00	-
1	YAMAHA REAR WHEEL SHAFT	SERVICEABLE	50.00	-
1	YAMAHA REAR BRAKE CALIPER	SERVICEABLE	180.00	-
1	YAMAHA REAR BRAKE MASTER CYLINDER	SERVICEABLE	120.00	-
1	YAMAHA REAR BRAKE DISC	SERVICEABLE	95.00	-
1	YAMAHA EXHAUST MUFFLER	DENTED / BENT	400.00	400.00
1	YAMAHA EXHAUST COVER (SMALL)	SERVICEABLE	45.00	-
1	YAMAHA EXHAUST COVER (BIG)	GRAZED	65.00	65.00
1	YAMAHA EXHAUST GASKET	NECESSARY	15.00	15.00
1	YAMAHA FOOT STEP	TO REPAIR SEE LABOUR	65.00	-
1	YAMAHA RIDER FOOTREST (LEFT)	SERVICEABLE	25.00	-
1	YAMAHA PILLION FOOTREST (RIGHT)	DISTORTED	25.00	25.00
1	YAMAHA PILLION FOOT REST BRACKET (RIGHT)	BROKEN	65.00	65.00
1	YAMAHA BRAKE PEDAL	BENT	45.00	45.00
1	YAMAHA HANDLEBAR	DISTORTED	95.00	95.00
1	YAMAHA HANDLEBAR BRACKET	SERVICEABLE	65.00	-
1	YAMAHA STEERING CONE	SERVICEABLE	95.00	-
1	SET YAMAHA REAR SIGNAL LIGHT	BROKEN (RIGHT)	90.00	90.00
1	YAMAHA REAR TAIL LIGHT	SERVICEABLE	365.00	-
1	SET YAMAHA BAR END BALANCER	MISSING (RIGHT)	45.00	45.00
1	SET YAMAHA GRIP	SERVICEABLE	35.00	-
1	YAMAHA REAR NUMBER PLATE HOLDER	GRAZED	80.00	80.00

Report Ref No. CS3/SMR21005143/Gty3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	YAMAHA REAR NUMBER PLATE HOLDER BRACKET	TO REPAIR SEE LABOUR	50.00	-
1	YAMAHA REAR NUMBER PLATE LIGHT ASSMEBLY	SERVICEABLE	60.00	-
	LESS 10% DISCOUNT		-	-106.50
			4,255.00	958.50
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE REAR (SN)	BENT	20.00	10.00
1	KAPPA BOX RACK (SN)	SERVICEABLE	180.00	-
1	KAPPA BOX BASE PLATE (SN)	SERVICEABLE	85.00	-
1	KAPPA BOX 39L (SN)	SCRATCHED	280.00	150.00
			565.00	160.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE FRONT RIM, FRONT WHEEL BEARING, AXLE SHAFT, TRIPPLE CLAMPS, FRONT FORK, STEERING CONE, FRONT BRAKE DISC.	NOT NECESSARY	250.00	-
	TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF YAMAHA FOOT STEP AND YAMAHA REAR NUMBER PLATE HOLDER BRACKET.		500.00	200.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	550.00	-
	TOWING-WORKSHOP TO ACCIDENT REPORTING CENTER.		60.00	30.00
	TOWING-ACCIDENT REPORTING CENTER TO WORKSHOP.		60.00	30.00
			1,420.00	260.00
GRAND TOTAL			6,240.00	1,378.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS3/SMR21005143/Gty3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.