

EQUATOR BROTHERHOOD®

REGISTRATION NO:53232274J

25 Kaki Bukit Road 4

Date:

28 March 2022

Synergy@KB #03-79

Singapore (417800)

Email:

equator.brotherhood@gmail.com

OFFICIALINVOICE

Name:

VIJAYAN D RAMASAMY @ VIJAYAN S/O D RAMASAMY

Make&Model:

YAMAHA / MX KING T150 MANUAL

Vehicle No:

FBR 8944E

SN	Item Description	Quantity	Unit Price	Amount
1	Cost of repairs	1	\$ 3,200.00	\$ 3,200.00
2				
3				
4				
5				
6				-
7				
8				
9				
10				
			Total Amount:	\$ 3,200.00

This is a computer generated invoice. No signature is required.

Equator Brotherhood®
REGISTRATIONNO:53232274J



159, Yishun St 11, #04-166. S(760159) Bussiness Regn No: 201416413W Tel/ Fax no: 67568321

Tax Invoice

VIJAYAN S/O D RAMASAMY

Invoice No.

: AAC 22 MAR 06

c/o EQUATOR BROTHERHOOD

Blk 25, Kaki Bukit Rd 4 Synergy@KB, #03-79

Singapore 417800

Invoice Date

: 18-Mar-2022

Terms

: 30 Days

Ref No.

: TP/FBR8944E/EB/0421/05

Vehicle No.

: FBR8944E

Date of Accident

: 10-Apr-2021

Date of Survey

16-Apr-2021

Description

Amount

SGD \$480.00

(1) Survey Of Vehicle

- A set of survey report

- Correspondence & Consultation

(2) Transportation Charges including resurvey

(3) Attached Photographs (40 pcs)

Total

SGD \$480.00

GRAND TOTAL

SGD \$480.00

E. & O.E.

Cheque should be crossed and made payment to "Advanced Automotive Consultancy Pte Lltd "

OMOTIVE **Authorised By**



Bussiness Regn No: 201416413W

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

1 REFERENCE

Our reference no

: TP/FBR8944E/EB/0421/05

Date of request Date of survey : 16-Apr-2021 : 16-Apr-2021

Date of accident

: 10-Apr-2021

Requested by

10-Apr-2021

.

: VIJAYAN S/O D RAMASAMY

C/o , Blk 25 Kaki Bukit Rd 4 Synergy@KB, #03-79.Singapore 417800

Type of claim

: Third party

Workshop

: EQUATOR BROTHERHOOD

Blk 25, Kaki Bukit Rd 4 Synergy@KB, #03-79

Singapore 417800

2 DETAILS OF VEHICLE

Registration No.

: FBR8944E

Make & Model

: YAMAHA MX KING T150 MANUAL

Date of registration

: 17-Nov-2020

Engine No.

: G3E6E0592267

Engine Capacity

: 150CC

Chassis No.

: MH3UG0750LK072816

Speedometer reading

. _

Colour

: BLUE

3 STATIC CHECK

Steering

: Affected

Paintwork

: Good

Footbrake

: In order

Modification

Nil

Handbrake

: In order

General condition

Good

TYRE CONDITION

Nearside/Make

Size

Front tyre

: 3mm/Dunlop

90/80-17

Rear tyre

: 3mm/Dunlop

120/70-17

5 POINT OF IMPACT

The said vehicle has sustained an impact damages on the rear, right and left portion. Kindly refer to the attached photographs for more detail of the damages.

6 REMARK

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.

Address: 159, Yishun St 11, #04-166. S(760159)

Annex A: Assessement / Adjustment on Spare Parts

ltem	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
	List Items					
1	Yamaha fairing (colored)	scratched	1	\$450.00	10%	\$405.0
2	Yamaha fairing (matte black)	deformed	1	\$140.00	10%	\$126.0
3	Yamaha swingarm	distorted	1	\$480.00	10%	\$432.0
4	Yamaha swingarm shaft	distorted	1	\$80.00	10%	\$72.0
5	Yamaha swingarm bushing kit	necessary	1	\$120.00	10%	\$108.0
6	Yamaha swingarm bearing kit	necessary	1	\$80.00	10%	\$72.0
7	Yamaha rear suspension	serviceable	1	\$380.00	100%	\$0.0
8	Yamaha rear rim	warped/wobble	1	\$280.00	10%	\$252.0
9	Yamaha rear wheel bearing	rattle	2	\$70.00	10%	\$63.0
0	Yamaha rear wheel shaft	serviceable	1	\$50.00	100%	\$0.0
1	Yamaha rear brake caliper	intact	1	\$180.00	100%	\$0.0
2	Yamaha rear brake master cylinder	intact	1	\$120.00	100%	\$0.0
3	Yamaha rear brake disc	intact	1	\$95.00	100%	\$0.0
5	Yamaha exhaust muffler	dented/bent	1	\$400.00	10%	\$360.
6	Yamaha exhaust cover (small)	intact	1	\$45.00	100%	\$0.
7	Yamaha exhaust cover (big)	grazed	1	\$65.00	10%	\$58.
8	Yamaha exhaust gasket	necessary	i	\$15.00	10%	\$13.
9	Yamaha foot step	repair	1	\$65.00	100%	\$0.
0	Yamaha rider footrest (left)	grazed	1	\$25.00	10%	\$22.
11	Yamaha pillion footrest (right)	distorted	1	\$25.00	10%	\$22.
2	Yamaha pillion foot rest bracket (right)	broken	1	\$65.00	10%	\$58.
3	Yamaha brake pedal	bent	1	\$45.00	10%	\$40.
4	Yamaha handlebar	distorted	1	\$95.00	10%	\$85.
5	Yamaha handlebar bracket	serviceable	1	\$65.00	100%	\$0.0
6	Yamaha steering cone	intact	1	\$95.00	100%	\$0.0
7	Yamaha rear signal light set	broken (right)	1	\$90.00	10%	\$81.0
8	Yamaha rear tail light	intact	1	\$365.00	100%	\$0.0
9	Yamaha bar end balancer set	missing (right)	1	\$45.00	10%	\$40.
0	Yamaha grip set	necessary	1	\$35.00	10%	\$31.
1	Yamaha rear number plate holder	grazed	1	\$80.00	10%	\$72.0
2	Yamaha rear number plate holder bracket	repair	1	\$50.00	100%	\$0.0
3	Yamaha rear number plate light assembly	intact	1	\$60.00	100%	\$0.0
			-	\$4,255.00	-	\$2,416.5

TP/FBR8944E/EB/0421/05

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
	S/Nett Items					
1	Number plate rear	bent	1	\$20.00		\$20.00
2	Kappa box rack	shifted	1	\$180.00		\$180.00
3	Kappa box base plate	necessary	1	\$85.00		\$85.00
4	Kappa box 39L	scratched	1	\$280.00		\$280.00
			-	\$565.00		\$565.00
		Total for Spare	Parts :	\$4,820.00		\$2,981.50

Annex B : Adjustment on Labour and Spray Painting

Т	P	F	B	R	8	94	44	F	F	B	10	142	1	10	75	,
- 1			\mathbf{D}		U	7"	+4	_/		\square		142		11	Ju	

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	To remove & replace front rim, front wheel bearing, axle shaft, tripple clamps, front fork, steering cone, front brake disc.	\$250.00	\$180.00
2	To remove & replace above body damaged parts,check wiring & lighting system	\$500.00	\$350.00
3	To conduct chassis alignment	\$550.00	\$400.00
4	Towing -workshop to accident reporting center	\$60.00	\$60.00
5	Towing -accident reporting center to workshop	\$60.00	\$60.00
		\$1,420.00	\$1,050.00
	TOTAL FOR LABOUR & SPRAY PAINTING:	\$1,420.00	\$1,050.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$4,820.00	\$2,981.50
TOTAL FOR LABOUR & SPRAY PAINTING :	\$1,420.00	\$1,050.00
TOTAL REPAIR COSTS:	\$6,240.00	\$4,031.50

TP/FBR8944E/EB/0421/05

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Equator Brotherhood estimated repair cost is \$\$6,240.00 and we have adjusted it to \$\$4,031.50 on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of \$\$3,200.00, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 4 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,

Henry Low

CMTM, DMTM, IPTM (UNF)

Automotive License Appraiser



















