

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI22005023/VNY3E2

**Date:** 20/07/2022

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MM000793  
Claimant Vehicle No : SHB3111M Insured Vehicle No : SMN8272B  
Date of Loss: 26/05/2022 Nature of Claim: TP Claim No: M2202689

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB3111M**  
Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU298670  
Reg. Date: 24/07/2019 (Man. Year: 2019) Chassis No: KMH851CVKU164822  
Colour: Yellow Odometer: 0 km  
Engine Capacity: 1580 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm  
Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,540.56	621.60	918.96	59.65
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	840.00	660.00	180.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,391.56</b>	<b>1,292.60</b>	<b>1,098.96</b>	<b>45.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>167.41</b>	<b>90.48</b>	<b>76.93</b>	<b>45.95</b>
<b>Nett Amount (S\$)</b>	<b>2,558.97</b>	<b>1,383.08</b>	<b>1,175.89</b>	<b>45.95</b>

### INSPECTION

Date of Assignment: 27/05/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)  
Date Inspected: 27/05/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969  
Estimated Period of Repair: 2.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 20 Jul 2022)

**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHB3111M)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL	
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL	
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Cut	451.25 FL	*461.25 FL	
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL	
5	1		*ANTENNA SMARTKEY	Serviceable	40.50 FL	*- FL	
6	1		*REAR BUMPER FOG LAMP	Serviceable	201.50 FL	*- FL	
7	1		*REAR BUMPER RUBBER MAT	Serviceable	50.00 F	*- F	
8	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F	
9	1		*REAR BUMPER REVERSE SENSOR	Cut	180.00 F	*180.00 F	
					<b>Sub Total (\$)</b>	<b>1,854.45</b>	<b>718.25</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	313.89	96.65
					<b>Total Parts (\$)</b>	<b>1,540.56</b>	<b>621.60</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
			<b>Sub Total (\$\$)</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHECK ALL LIGHTING	New	60.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >