

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005031/UEA3Q2**Date:** 12/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993603
Claimant Vehicle No :	YQ1752X	Insured Vehicle No :	GBH2933D
Date of Loss:	26/05/2022	Nature of Claim:	TP
		Claim No:	7478485021SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ1752X		
Make & Model:	MITSUBISHI FUSO, 7.5 D FK62FMZ1RDEC (M)	Engine No:	6M60257200
Reg. Date:	16/10/2019 (Man. Year: 2019)	Chassis No:	FK62FMA40147
Colour:	White	Odometer:	88836 km
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/70 R19.5	Rear Tyre Size:	265/70 R19.5 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,596.90	1,707.67	3,889.23	69.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	740.00	200.00	540.00	72.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,336.90	1,907.67	4,429.23	69.90
+ Loss of Use (3.0 x S\$140.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,335.12		
Global Sum Settlement (S\$)		2,330.00		

INSPECTION

Date of Assignment:	30/05/2022	
Date Inspected:	30/05/2022 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Serviceable	2,360.00 F	*- FL
2	1		*FRONT WINDSCREEN GLASS WEATHERSTRIP	Not Necessary	691.50 F	*- FL
3	1		*FRONT LH MIRROR ARM	Bent / Damaged	1,923.60 F	*1,655.10 FL
4	1		*FRONT LH MIRROR ARM HOLDER TOP	Bent	80.40 F	*80.40 FL
5	1		*FRONT LH MIRROR ARM BRACKET LOWER	Cut	50.70 F	*50.70 FL
6	1		*FRONT LH SIDE MIRROR ROUND	Broken	142.00 F	*142.00 FL
7	1		*FRONT LH SIDE MIRROR SQUARE	Cut	188.80 F	*188.80 FL
8	1		*FRONT LH SIDE MIRROR RECTANGLE	Cut	159.90 F	*159.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,596.90	2,276.90
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	569.23
Total Parts (\$)	5,596.90	1,707.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST	New	240.00	0.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	300.00	200.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	200.00	0.00
Gross Labour Cost (\$\$)			740.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >