

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT LONPAC INSURANCE BHD CS3/LPC22005037/Eqy3m4 Ref: 300 BEACH ROAD Date: 13/06/2022 #17-04/07 THE CONCOURSESINGAPORE 199555 Code: LPC2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBA 5219A** SKT 3771C Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 21/22/22/VC00/025851 Excess (\$) 0.00 **GERALD POH Assign From Assign Date** 27/05/2022 2. **Vehicle Particulars & Condition** TOYOTA ALTIS 1598 Make & Model C.C HIDDEN Engine No. Year of Reg. MR053REH104533575 **BLUE** Chassis No. Colour 141788 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/55 R16 DUNLOP 4 mm DUNLOP L/H Front Tyre 205/55 R16 4 mm 205/55 R16 DUNLOP R/H Rear Tyre 4 mm 205/55 R16 DUNLOP 4 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 26/05/2022 01/06/2022 (03:52 PM) Inspect Date / Time Accident Date TRINICE AUTOMOBILE SERVICES Survey held at BLK 1001 BUKIT MERAH LANE 3 #01-63 SINGAPORE 159724 5a. Remarks

Report Ref No. CS3/LPC22005037/Eqy3m4

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser