#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Our File No: CC3/AIG22005044/ENCE2

Singapore 079120 Date: 20/09/2022

**REFERENCE** 

Insured/Claimant: TAY SOH ENG Policy No: 7220007807

Date of Loss: 24/05/2022 Nature of Claim: OD Claim No: 3964749849SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SND7641S

Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A) Engine No: DEM035355

Reg. Date: 24/01/2022 (Man. Year: 2021) Chassis No: WAUZZZF46NN002872

Colour: Grey Odometer: 5570 km

Engine Capacity: 1984 cc
Market Value/New Car Price: \$\$230,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		24,600.00	11,146.40	13,453.60	54.69
Miscellaneous Items		0.00	0.00	0.00	
Labour		18,814.00	4,097.00	14,717.00	78.22
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	43,414.00	15,243.40	28,170.60	64.89
	- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
	(S\$)	42,314.00	14,143.40	28,170.60	66.58
	+ GST 7.00/7.00% (S\$)	2,961.98	990.04	1,971.94	66.58
	Nett Amount (S\$)	45,275.98	15,133.44	30,142.54	66.58

INSPECTION

Date of Assignment: 30/05/2022

Date Inspected: 27/05/2022 Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken		*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Bent	79.00 FS	*63.20 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Broken	293.00 FS	*234.00 FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Broken	51.00 FS	*40.08 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	Not Necessary	293.00 FS	*-FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	151.00 FS	*120.40 FS
8	1		*FRONT BUMPER TRIM - RH	Cut	54.00 FS	*42.64 FS
9	1		*RADIATOR GRILLE	Not Necessary	1,754.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*-FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	212.00 FS	*-FS
12	1		*FRONT BUMPER GUIDE SECTION - RH	Broken	41.00 FS	*32.24 FS
13	1		*FRONT BUMPER BRACKET - RH	Not Necessary	254.00 FS	*-FS
14	1		*FRONT BUMPER TOP COVER	Cut	143.00 FS	*114.00 FS
15	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
16	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
17	1		*FRONT BUMPER LOCK CARRIER BRACKET	Broken	154.00 FS	*122.80 FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*-FS
19	4		*FRONT BUMPER POP RIVET	Not Necessary	4.00 FS	*- FS
20	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	530.00 FS	*-FS
21	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*-FS
22	1		*HORN - RH	Not Necessary	139.00 FS	*-FS
23	1		*HORN SUPPORT - RH	Not Necessary	33.00 FS	*-FS
24	1		*FRONT FENDER - RH	Dented	1,227.00 FS	*981.60 FS
25	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*-FS
26	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	81.00 FS	*64.24 FS
27	1		*FRONT FENDER BRACKET - RH	Bent	41.00 FS	*32.72 FS
28	1		*FRONT FENDER BRACKET CENTER - RH	Bent	55.00 FS	*44.00 FS
29	1		*FRONT FENDER POP RIVET (7PCS)	Necessary	27.00 FS	*21.28 FS
30	1		*FRONT FENDER BRACKET END - RH	Not Necessary	36.00 FS	*-FS
31	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
32	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	37.00 FS	*-FS
33	1		*FRONT FENDER TOP CAP - RH	Not Necessary	13.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING LINER - RH	Crushed	262.00 FS	*209.60 FS
35	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*-FS
36	1		*FRONT WHEEL SPOILER - RH	Broken	82.00 FS	*65.12 FS
37	1		*FRONT WHEEL SPOILER LOWER - RH	Not Necessary	40.00 FS	*-FS
38	1		*FRONT FENDER LEDGE COVER LONG - RH	Broken	35.00 FS	*27.52 FS
39	1		*HEADLAMPS COVER - RH	Broken	49.00 FS	*38.64 FS
40	1		*FRONT FENDER LEDGE COVER - RH INNER	Not Necessary	68.00 FS	*-FS
41	1		*HEADLIGHT - RH	Broken		*6,537.60 FS
42	1		*HEADLIGHT HOSE	Not Necessary	42.00 FS	*-FS
43	1		*SPACER (3PCS)	Bent	136.00 FS	*107.84 FS
44	1		*CABLE TIES	Not Necessary	2.00 FS	*-FS
45	1		*LIFT CYLINDER - RH	Broken	231.00 FS	*184.40 FS
46	1		*LIFT CYLINDER BRACKET	Missing	7.00 FS	*5.44 FS
47	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*-FS
48	1		*LIFT CYLINDER CORRUGATED PIPE - RH	Not Necessary	53.00 FS	*-FS
49	1		*WASH WATER RESERVOIR	Not Necessary	160.00 FS	*- FS
50	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*-FS
51	1		*LOCK CARRIER SUPPORT - RH	Not Necessary	43.00 FS	*- FS
52	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
53	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*-FS
54	1		*RADIATOR AIR GUIDE - RH	Not Necessary	51.00 FS	*- FS
_			Report was unsubmitted during this print	-out		

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Not Necessary	38.00 FS	*-FS
56	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
57	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
58	1		*FRONT FENDER CONNECTING PLATE - RH LOWER	Repair	279.00 FS	*- FS
59	1		*FRONT FENDER CONNECTING PLATE - RH UPPER	Repair	241.00 FS	*- FS
60	1		*NOISE INSULATION	Not Necessary	640.00 FS	*- FS
61	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	Not Necessary	344.00 FS	*- FS
62	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
63	1		*RHS FRONT RIM (NPA)	Not Necessary	0.00 FS	*-FS
64	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
65	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
66	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
67	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
68	1		*SUNDRIES	Necessary	600.00 FS	*31.20 FS
69 F=Fra	1 anchise	part. S=Spc	*SET FRONT BUMPER WIRING Nett.	Not Necessary	642.00 FS	*-FS
		·		Total Parts (S\$)	24,600.00	11,146.40

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,400.00	0.00
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	New	800.00	0.00
6	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR	New	280.00	0.00
7	TO SETUP VEHICLE CAR O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
8	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR BONNET. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED		6,500.00	1,250.00
9	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER TOP SUPPORT, RHS FRONT FENDER AND RHS FRONT DOOR	New	4,500.00	1,925.00
10	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	0.00
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
	Gross Labour	r Cost (S\$)	18,814.00	4,097.00
	Report was unsubmitted during this	nrint-out		
	report was ansabilitied during tins	print-out.		

< END OF ESTIMATES >