

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005052/BPA3Q2**Date:** 28/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210128085
Claimant Vehicle No :	SKZ2602H	Insured Vehicle No :	GBL5788R
Date of Loss:	28/05/2022	Nature of Claim:	TP
		Claim No:	6805589650SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ2602H	Engine No:	L15B4026113
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11106124
Reg. Date:	15/01/2016 (Man. Year: 2015)	Odometer:	66833 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Tourador 5 mm	Rear Left Side:	Tourador 5 mm
Front Right Side:	Tourador 5 mm	Rear Right Side:	Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,387.60	17,221.68	15,165.92	46.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,450.00	4,180.00	5,270.00	55.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,837.60	21,401.68	20,435.92	48.85
Approved Total (Overridden) (S\$)		17,100.00		
(S\$)	41,837.60	17,100.00	24,737.60	59.13
+ GST 7.00/7.00% (S\$)	2,928.63	1,197.00	1,731.63	59.13
Nett Amount (S\$)	44,766.23	18,297.00	26,469.23	59.13
+ Car Rental (14.0 x S\$100.00/day + 7.00% GST) (S\$)		1,498.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		19,862.45		
Global Sum Settlement (S\$)		19,800.00		

INSPECTION

Date of Assignment:	30/05/2022	
Date Inspected:	30/05/2022	Inspected At: 160 SIN MING DR
		#01-14 SIN MING AUTO CITY
		Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)
Estimated Period of Repair:	12.0 days	

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,436.20 FL	*1,100.00 FL
2	1		*TAILGATE LOGO	Necessary	95.80 FL	*50.00 FL
3	2		*TAILGATE LAMP	Broken	1,092.00 FL	*826.00 FL
4	1		*TAILGATE INNER LOCK	Jammed	156.70 FL	*156.70 FL
5	1		*TAILGATE OUTER GARNISH	Not Damaged	385.00 FL	*- FL
6	1		*TAILGATE INNER TRIMBOARD	Broken	386.20 FL	*153.00 FL
7	1		*TAILGATE WEATHERSTRIP	Torn	198.40 FL	*198.40 FL
8	1		*TAILGATE INNER HANDLE	Not Damaged	85.00 FL	*- FL
9	1		*TAILGATE ANTENNA SENSOR	Broken	214.00 FL	*100.00 FL
10	1		*TAILGATE SMART BUZZER	Not Damaged	195.00 FL	*- FL
11	1		*REAR W/SCREEN MOULDING SIDE	Necessary	88.60 FL	*88.60 FL
12	1		*REAR W/SCREEN MOULDING TOP	Necessary	108.00 FL	*108.00 FL
13	1		*REAR W/SCREEN MOULDING BOTTOM	Necessary	108.00 FL	*108.00 FL
14	1		*REAR BUMPER	Broken	989.50 FL	*763.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	170.00 FL	*170.00 FL
16	2		*REAR BUMPER BRACKET	No such part	271.20 FL	*- FL
17	2		*REAR BUMPER REFLECTOR	Broken	256.00 FL	*256.00 FL
18	2		*REAR BUMPER SIDE GARNISH	Broken	477.80 FL	*400.00 FL
19	1		*REAR END PANEL	Dented	695.80 FL	*544.00 FL
20	1		*REAR END PANEL TOP GARNISH	Broken	184.00 FL	*184.00 FL
21	1		*SPARE TYRE PANEL	Dented	1,230.00 FL	*741.00 FL
22	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	420.00 FL	*- FL
23	1		*SPARE TYRE PANEL INSULATOR	No such part	240.00 FL	*- FL
24	1		*SPARE TYRE PANEL TOOLS TRAY	Broken	264.00 FL	*264.00 FL
25	1		*SPARE TYRE PANEL LOWER SPLASH COVER	Not Damaged	316.00 FL	*- FL
26	2		*REAR FENDER	Not Damaged	2,851.60 FL	*- FL
27	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,446.00 FL	*- FL
28	2		*REAR FENDER ARCH GARNISH	Not Damaged	436.60 FL	*- FL
29	2		*TAILLAMP	Broken	1,316.60 FL	*974.00 FL
30	1		*EXHAUST PIPE	Not Damaged	895.00 FL	*- FL
31	2		*EXHAUST MOUNTING	Not Damaged	85.00 FL	*- FL
32	1		*EXHAUST HEAT SHIELD	Not Damaged	185.00 FL	*- FL
33	1		*BONNET	Dented	1,034.70 FL	*855.00 FL
34	1		*BONNET LOCK ASSY	Jammed	234.60 FL	*95.00 FL
35	1		*FRONT BUMPER	Broken	1,050.00 FL	*762.00 FL
36	1		*FRONT BUMPER LOWER	Broken	485.60 FL	*250.00 FL
37	2		*FRONT BUMPER SIDE RETAINER	Necessary	144.00 FL	*144.00 FL
38	1		*FRONT BUMPER REINFORCEMENT	Bent	486.00 FL	*321.00 FL
39	1		*FRONT BUMPER CENTRE GRILLE	Broken	198.60 FL	*198.60 FL
40	2		*FRONT BUMPER FOG LAMP	Broken	913.40 FL	*720.00 FL
41	2		*FRONT BUMPER FOG LAMP GARNISH	Broken	252.40 FL	*252.40 FL
42	1		*FRONT BUMPER TOW CAP	Not Damaged	83.20 FL	*- FL
43	2		*FRONT GRILLE TOP BRACKET SIDE	Broken	174.60 FL	*174.60 FL
44	1		*FRONT GRILLE TOP BRACKET CENTRE	Broken	198.00 FL	*90.00 FL
45	1		*FRONT GRILLE	Broken	642.30 FL	*500.00 FL
46	2		*HEADLAMP ASSY	Broken	4,291.80 FL	*3,718.00 FL
47	2		*HEADLAMP BRACKET	Broken	152.00 FL	*110.00 FL
48	1		*FRONT SUPPORT PANEL	Dented	898.00 FL	*796.00 FL
49	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	185.00 FL	*185.00 FL
50	2		*FRONT FENDER	Dented	1,570.00 FL	*970.00 FL
51	2		*FRONT FENDER ARCH GARNISH	Not Damaged	257.80 FL	*- FL
52	1		*AIRCON CONDENSER	Bent	985.00 FL	*920.00 FL
53	1		*AIRCON SUCTION HOSE	Not Damaged	398.00 FL	*- FL
54	1		*AIRCON DISCHARGE HOSE	Not Damaged	352.00 FL	*- FL
55	1		*RADIATOR	Bent	987.90 FL	*987.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
57	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
58	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
59	2		*TAILGATE LAMP CLIPS	Necessary	100.00 FS	*30.00 FS
60	2		*TAILGATE LAMP SEAL	Necessary	120.00 FS	*40.00 FS
61	1		*TAILGATE INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
62	1		*TAILGATE WINDSCREEN CLIPS	No such part	50.00 FS	*- FS
63	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
64	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
65	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*20.00 FS
66	1		*REAR BUMPER CHROME PROTECTOR	Not Necessary	365.00 FS	*- FS
67	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
68	2		*REAR BUMPER SIDE GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
69	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
70	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
71	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
72	1		*SPARE TYRE PANEL LOWER SPLASH COVER CLIPS	Necessary	50.00 FS	*20.00 FS
73	2		*REAR FENDER SEALANT	Not Necessary	200.00 FS	*- FS
74	2		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
75	2		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
76	1		*REAR CHASSIS MEMBER SEALANT	Not Necessary	100.00 FS	*- FS
77	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*20.00 FS
78	2		*TAILLAMP SEAL	Necessary	120.00 FS	*20.00 FS
79	1		*REAR NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS
80	1		*REVERSE CAMERA	Not Damaged	480.00 FS	*- FS
81	2		*REAR BUMPER REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
82	1		*BONNET SEALANT	Necessary	100.00 FS	*30.00 FS
83	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
84	1		*FRONT BUMPER LOWER CLIPS	Necessary	50.00 FS	*20.00 FS
85	1		*FRONT BUMPER CENTRE GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
86	2		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
87	1		*FRONT BUMPER CHROME PROTECTOR	Not Necessary	295.00 FS	*- FS
88	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
89	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
90	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
91	2		*FRONT FENDER SEALANT	Not Necessary	200.00 FS	*- FS
92	2		*FRONT FENDER ARCH GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
93	1		*RADIATOR COOLANT	Necessary	80.00 FS	*30.00 FS
94	1		*AIRCON FLUID	Necessary	80.00 FS	*40.00 FS
95	1		*FRONT NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS
96	2		*BONNET HINGE	Bent	178.00 FL	*178.00 FL
97	1		*INTAKE MANIFOLD	Broken	897.40 FL	*897.40 FL
98	1		*INTAKE MANIFOLD HOSE	Torn	130.20 FL	*80.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	39,279.50	21,299.60
- List Item Discount on L Items 20.00/20.00% (\$)	6,891.90	4,077.92
Total Parts (\$)	32,387.60	17,221.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R REVERSE CAMERA	New	150.00	0.00
5	R&R EXHAUST PIPE	New	150.00	0.00
6	REAR CHECK WIRING	New	100.00	30.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REAR UPHOLSTERY	New	300.00	0.00
9	REAR PANEL BEATING	New	1,800.00	1,200.00
10	REAR RUST PROOFING	New	200.00	0.00
11	REAR SPRAY PAINTING	New	1,800.00	600.00
12	R&R BONNET COMPONENT	New	150.00	60.00
13	R&R CONDENSER	New	150.00	60.00
14	R&R RADIATOR	New	150.00	60.00
15	FRONT CHECK WIRING	New	100.00	30.00
16	DIAGNOTIC AND RESET FAULT CODE	New	300.00	0.00
17	FRONT UPHOLSTERY	New	300.00	0.00
18	FRONT PANEL BEATING	New	1,200.00	800.00
19	FRONT RUST PROOFING	New	200.00	0.00
20	FRONT SPRAY PAINTING	New	1,200.00	1,000.00
21	R&R INTAKE MANIFOLD	New	200.00	80.00
22	LABOUR	New	400.00	0.00
Gross Labour Cost (\$\$)			9,450.00	4,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >